REMON. COR. 1-6, WILLIAMS TWP. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

SECTION

For corners in Bay (County)	Located in:	Corner Code #
1. Public Land Survey	T 14N R 3E T R T R	1-6
 Property Controlling in Section Miscellaneous Property in Sec. 	T R R S T R S T R R S T R R S T R R R R	
4. Lot No, Recorded	1 Plat	

1999 DEC 28 P 1: 02

Barber Torla Du France REGISTER OF DEEDS BAY COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

5. Private Claims I, <u>JERRY L. JONES</u>, in a field survey on <u>June 8</u>, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the interior, Bureau of Land Management or by a decree of a Court of Law with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below: monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

ABCDE	F G	н 1	J K	LM
6 + 5 +	4	3	2	. i 🚽
3 + + +				
4-7-8 +	9	10	11 1	12 7
6 18 + 17	- 16	15	14	13 -
8 19 7 20	21	- 22	23	24
9 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1 -1	28 -	27-	26 -	- 25
11 31 - 32 -	33 -	34	35 -	36 -
13 1 1 1 1 1 1 1 1 1	J			

- A. Description of original monument and accessories and/or subsequent restoration:
- 1/2 corner common to Sections 14 and 15 1-6

Survey by Glo, 1031, set post Survey by Edmands Engineering, 1974, 1981, found ¾" iron & stone Survey by Ledy Engineering, 1987, found ¾" pipe Survey by D. Burgin, 1992, found ¾" pipe Survey by Wade-Trim, 1998, found 3/4" pipe LCRC by M. MacDonald, 1979, found 3/2" pipe LCRC by D. Ledy, 1988, found 3/4" pipe



- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 1/2 corner common to Sections 14 and 15 1-6

Found 3/8° rod per surveys by Edmands Engineering, Ledy Engineering, D. Burgin, Wade-Trim and LCRC's by M. MacDonald and D Ledy

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.
- 1/4 corner common to Sections 14 and 15 1-6

Replaced 3/8" rod with 5/8" rod and brass cap stamped Bay County Remonumentation PS 19838 in monument box and is accepted as the best available evidence of the position of the accepted corner.

N 15 Deg W, 157.10', nail and disc in power pole
N 15 Deg E, 169.56', spike in power pole (Rec. as 169.62' in 1988 LCRC)
S 89 Deg E, 72.92', spike in twin 12" Oak (Rec. as 72.90' in 1988 LCRC)
N 45 Deg E, 137.24', NW corner house (foundation)

0.2' West of West edge Garfield Road (Bit.)

Signed by Surveyor's Michigan License No. 19838

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971 Revised May 14, 1971 Revised Jan., 1983

004

APPROVED LAND CORNER

Michael MacDonald P.S. County Tepresentative