SECTION

REMON. COR. I-10 WILLIAMS TWP.

	Open sales. 41	LAND CORN	ER RECORDATION CE	RTIFICA	TE							
For co	omers in	raing Requi	rement of Act 74, Mich), P.A. 191	70	_	_	Ž				
	(County)	Located in:	Corner Code #			נָ	REG		D 8861			
1. Pul	blic Land Survey	T 14N R 3E T R	<u>l-10</u>			000	GISTER O		DEC -7		עבייט	ם חים סים
	operty Controlling S Section S	T R T R T R T R T R T R T R T R T R T R				THE COLUMN	F DEEDS	è S	⊳		עביטאשבט	ת ח ס
3. Mis	cellaneous S	T R -					E		'n			
		TR		Registe	er of (Deeds	Stamp	& File	Numb	er		
4. Lot 5. Priv	No, Recorded Plat /ate Claims				A E	3 C	D E	F	G H	īi	J K	L M
that unclines 1 a in the cointerior, corner pof the Minonument	Y JONES, in a field survey on July 9, 199 for requirements of P.A. 74, Michigan P.J. and 2 above were in conformance with resurrent manual of survey instructions of Bureau of Land Management or by a depoints mentioned in lines 3, 4 and 5 about the surveyors or by a sented, re-monumented, recovered, found: Not more than 2 corners, all in recorded on this certificate.	to of 1970, the corner egulations and rules the United States ecree of a Court of the were in conform Decree of a Court if as expressed belo	r points mentioned on therefore as required Department of the Law and/or that the mance with the rules of Law; re-established, w:	2 3 4 5 6 7 8 9 10 11 12 13		5 	-5- -8- -17- -20- -29- -32-	-4- -9- -16 -21- -28- -33-	-3- -10 -15 -22 -27	51 22	23-26-35-	-1- -12- -13- -24- -25- -36-
	scription of original monument an		nd/or subsequent resto	ration:								
ŀ10	1/4 corner common to Sections 26 and Survey by Glo, Harvey Parke, 1831, set Survey by Edmands Engineering, 1969 LCRC by G. Delamater, 1971, found co LCRC by L. McGinnis, 1972, set railroa	post), 1971, 1972, 1973, mer	1975, 1982, 1986, set nail, se	et capped in	on	*		6.	ال الا	nnes Care	3	A 10
WITNE	SS NOTE: Witnesses from above presented to peer rev	surveys and L(liew committee	CRC's are available in de and is on file at the Reg	ossier file; Ister of De	; whi eds	ich w Offic	as e.	Tion to	D' /	TVEVO No. 9838)A	SOLUTION STATES
B. Des	cription of corner evidence found	and/or method	annlied in rectoring or	rooctablic	hine				STORE CON	19 1904	Profession of	•

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

110 1/4 corner common to Sections 26 and 27

Found 1/2" rod and cap in mon box per surveys by Edmands Engineering and LCRC's by G. Delamater and L. McGinnis

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

i-10 1/4 corner common to Sections 26 and 27

> Found 1/2" rod and cap in mon box per surveys by Edmands Engineering and LCRC's by G. Delamater and L. McGinnis, removed rod, dug found nothing, replaced rod with 5/8" road and brass cap stamped Bay County Remonumentation PS 19838, and is accepted as the best available evidence of the position of the accepted corner.

West, 39.73', nail and disc in power pole, Rec. 39.45 S 50 Deg W, 108.00', southeast corner of easterly part of house \$ 35 Deg E, 32.19', pk nail in mailbox post \$ 35 Deg W, 54.89', chiseled "+" in south end pipe East, 3.4', centerline Garfield Road, Rec. 2.8 on tree line to west

APPROVED LAND CORNER P.A. 345 OF 1990 - Bay County
Date 345ept 98
MJM

Michael MacDonald P.S. County Representative

Date

Surveyor's Michigan License No. 19838

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971