MAK 1 7 1999

## SECTION

## REMON. COR. I-11 WILLIAMS TWP. LAND CORNER RECORDATION CERTIFICATE

Colore Care II of the a la	Filing Requirement of Act 74, Mich. P.A. 1970									
For corners in Bay	i mig nequi	rement of ACt 74, MIC	ii. P.A. 1970 	BAY		8661		٠		
(County)	Located in:	Corner Code #	Í	COUN	6	330			Z Z	Ö
Public Land Survey	T <u>14N</u> R <u>3E</u> T R	<u> </u>		T K O					בטאטבו	ָ ว
	T R T			F DEEDS MICHIGAN	<b>\</b>	89 89			(UEU	į
2. Property Controlling S in Section S	_ T R			AN AN	N	'n				,
3. Miscellaneous S Property in Sec. S	T R T R		Register of Deeds Stamp & File Number							
4. Lot No, Recorded Plat										
5. Private Claims			АВ	CDI	F	G H	I	J	K	L
I. JERRY JONES, in a field survey on July 0	1000 do hosebu endik.		_ [_		1	T	1		-1-	$\overline{}$

that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

M 3 4 5 6 18 7 8 9 Ż0 21 22 23 9 10 30 29 28 26 25 11 12 31 13

MICHIGAN

**JERRY L** 

JONES

PROFESSIONAL

SURVEYOR No.

19838

A. Description of original monument and accessories and/or subsequent restoration:

**L11** Corner common to Sections 26, 27, 34 and 35

> Survey by Glo, Harvey Parke, 1831, set post Survey by M. Hunter, 1958, found Survey by Edmands Engineering, 1971, 1972, 1973, 1975, 1986, found iron Survey by Hunter and Whittler, 1973, found 5/8" rod Survey by Ledy, 1991, found 1/2" rod Survey by Wade-Trim, 1996, found 1/2" rod

ROFERSION WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee and is on file at the Register of Deeds Office.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 1-11 Corner common to Sectins 26, 27, 34 and 35

Found 1/2" rod and cap in mon box per surveys by M. Hunter, Edmands Engineering, Hunter and Whittier, Ledy, and Wade-Trim

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- **L11** Corner common to Sections 26, 27, 34 and 35

Found 1/2" rod and cap #29240 in mon box per surveys by M. Hunter, Edmands Engineering, Hunter and Whittier, Ledy, and Wade-Trim. Removed rod, dug, found nothing. Replaced rod with 5/8" rod and brass cap stamped Bay County Remonumentation PS 19838 and is accepted as the best available evidence of the position of the accepted corner.

N 45 Deg W, 51.55', pk nail in power pole (Rec. 51.35, 51.20, 51.56, 51.61) \$ 50 Deg W, 48.26', pk nail in power pole (Rec. 49.25, 48.30) S 45 Deg E, 51.80', pk nail in power pole (Rec. 51.25, 51.35, 51.78, 51.79) N 60 Deg E, 78.67', centerline top of hydrant (Rec. 78.64)

APPROVED LAND CORNER P.A. 345 OF 1990 - Bay County Sept 98 MJM Michael MacDonald P.S.

County Representative

Signed by

Date 12/01/98

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Surveyor's Michigan License No. 19838

Revised May 14, 1971

Revised Jan., 1983