1999

SECTION

REMON. COR. I-12 WILLIAMS TWP. LAND CORNER RECORDATION CERTIFICATE

For corners in Bay	Filing Requirement of Act 74, Mich. P.A. 1970			
(County)	Located in:	Corner Code #	In 1988	
Public Land Survey	T <u>14N</u> R <u>3E</u> TR TR	<u>l-12</u>		RECORDED
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R		HIGHIGAN Register of Deeds Stamp & File Number	RDED
Lot No, Recorded Plat Private Claims LIERRY IONES in a field arrange of the control of the				KL

JONES, in a field survey on August 11, 1998, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

4 5 6 ĺ8 6 7 8 20 21 24 9 10 30 29 28 Ż6 25 11 12

- A. Description of original monument and accessories and/or subsequent restoration:
- **F12** 1/4 corner common to Sections 34 and 35

Survey by Glo, Harvey Parke, 1831, set post Survey by Hunter and Whittier, 1971, 1973, 1977, found 3/8" rod Survey by Edmands Engineering, 1973, 1976, 3/8" iron LCRC by L. McGinnis, 1973, 3/8" iron

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossler file; which was presented to peer review committee and is on file at the Register of Deeds Office.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 1/4 corner common to Sections 34 and 35

Found 3/8" rod in mon box per surveys by Hunter and Whittier, Edmands Engineering, and LCRC by L. McGinnis



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 1-12 1/4 corner common to Sections 34 and 35

Found 3/8" rod in mon box per surveys by Hunter and Whittier, Edmands Engineering, and LCRC by L. McGinnis; removed rod, dug, found nothing, replaced rod with 5/8" rod and brass cap stamped Bay County Remonumentation PS 19838 and is accepted as the best available evidence of the position of the accepted corner.

S 88 Deg E, 17.58', northwest corner concrete headwalf

S 30 Deg E, 108.84', nail and BC disc in power pole, Rec. as 109.15

\$ 50 Deg E, 56.95', centerline 6" Maple

S 30 Deg W, 135.83', nail and disc in power pole

APPROVED LAND CORNER P.A. 345 OF 1990 - Bay County Date 24 Sept 78

MJH / Michael MacDonald P.S. **County Representative**

Jeny f. Jones

Date 12/01/98

Surveyor's Michigan License No. 19838

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971 Revised Jan., 1983

