MAY 2 0 1997

a the area arrived the

1996 BAY COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

003	32
-----	----

For corners in Located In: Corner Code # Bay (County) 1. Public Land Survey T14N. R6E. T14N. R6E. R Ç 3 2. Property Controlling **=** in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. _____, Recorded Plat 1 5. Private Claims 2 3 I, Ronald C. Prevost , in a field survey on 6-26-B-11, 4-30-C-11 , 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 5 above were in conformance with regulations and rules therefore as required in the current manual of survey 6 instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded 10 on this certificate. 11 12 A. Description of original monument and accessories and/or subsequent restoration: B-11 Post set by Risdon, 1834 C-11 Post set by Risdon, 1834 Point set by M.J. MacDonald, 1968 Iron set by Consumers Power Co., 1958 Recorded survey L798 P614, McGinnis, 1976 Point found by M.J. MacDonald, 1968 L.C.R.C. L2 Pg 540, 3/8" rod, Dunton, 1979 LCRC L2 P564 1/4" bolt/mon box Leach, 1984 Recorded survey L1215 P286 L.D. McGinnis, 1992 Co. Surveyor records undated. Iron. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: B-11 Found 3/8" rod 6" below bit. N.E. 51.45' (51.5R L2 P540)(51.45 R L798 P614) top hyd C-11 Found 1/4" bolt in Mon Box 5-4-96 S.E. 4.65'(4.5 R L2 P540)(4.5 R L798 P614) W. leg of South 2633.69 (2633.73R) L2 P564 to E 1/4 cor North 14' (14'R) & Road L2 P564 N.60°W. 57.02 (57.0 R L2 P564) top ctr hyd. sign. N.E. 41.55 (41.4 R L2 P540) nail & disc in power pole. Approved by Peer Group 6-27-96 S.45°E. 20.58 (20.58 R L2 P564) NE cor. Headwall Approved by Peer Group 6-27-96 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: B-11 Replaced 3/8" rod with 5/8" bar & Bay Co. Re-mon cap. C-11 Replaced 1/4" bolt with 5/8" bar, Bay Co. Re-mon cap in Placed mon box 9-30-96 existing M. box 9-30-96. N.45°E. 41.55 nail & disc in P. pole SE face. S.20°E. 4.65 W. leg of sign. N.50°W. 45.61 set Bay Co. Re-mon disc. In NE. face P. pole S.45°E. 64.42 set Bay Co. Re-mon disc in SE face P. pole. N.55°E. 51.45 top hyd. S.45°E. 20.58 NE. Cor. headwall. OF MOUNT N.46°E. 104.64 SW corner brick pillar, porch N.60°W. 57.02 top ctr. hyd. APPROVED LAND CORNER P.A. 345 OF 1990 - Bay County Date ジステンスを大 PREVOST MIM **PROFESSIONAL** Michael MacDonald P.S. SURVEYOR

County Representative

Surveyor's Michigan License No. 24612

Signed by /

2-23-96

24612 POFESSION PA