SURVEY & REMONUMENTATION

APR 2 6 1995

COMMISSION

Bay County Remonumentation

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	Bay	Located In:	0			88 AX	`			
	(County)	Located III.	Corner Code ##			38		28	22	
1.	Public Land Survey	T 15N _R . 3 5 T R	В 13					ധ	ECORD	
		T R T R					•	Ö Ez	020	
	Property Controlling in Section			13 1	159	ンド型 いない (4)	3 L	臣		
3.	Miscellaneous	S T R			まりむ iter of D	ande S	tamp l	9. Eila	Mumba	_
	Property in Sec.	S T R		negis		eads 3	тапр с			r
4.	Lot No, F	Recorded Plat								
5.	Private Claims				АВ	Ç D	EF(3 H	IJK	
					2 6-	<u>\$</u>	- 4	— å —	╁╌┇╌┧	- -
				:	3				╁┈╁╌╂	
_					4	8		—10	ֈ-ֈ-ֈ	12 -
	_	, in a field survey on June			5		-		$\downarrow \downarrow \downarrow \downarrow$	<u> </u>
	-	quirements of P.A. 74 Michigan P.A. n conformance with regulations a			6 18-	17	16	 15	14-1	 13
		uctions of the United States Depa			7				1-1-1	
Man	agement or by a decree of	a Court of Law and/or that the corn	er points mentioned in lines 3, 4 a	nd 5	8 19	20_		32		
		th the rules of the Michigan Board			اً او	ĬĬ	l îi l		ΤïΠ	
	rt of Law; established, i ressed below:	re-established, monumented, re	-monumented, recovered, found		0 30					
		orners, all in the same town a	and range may be upposeded		30—	29	28		20	25
NO	on this certificate.	•	and range, may be recorded		231	-32	-33	-34-	35	36-
Α.	Description of original	monument and accesso	nd/or subsequent restoration:	1.	3	11	Ll		1_1_1	

<u>B 13</u> Set 1/4 Section post - H. Parke - 1831.

Sugar 16" N 57° E 9 L.

Maple 20" N 45° W 15 L.

Consumers Power Company Survey - Set corner by single proportional measurement between A 13 and C 13 - 1968.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - <u>B 13</u> Standard 1/4 corner common to Section 31, T15N, R3E Search for corner per CPC survey did not find set pk nail by single proportion on line between A 13 and C 13, T15N, R3E per GLO Notes and CPC survey on centerline of East-West Townline Road and 14'+ East of fence line to North. Monument accepted as a careful and faithful re-establishment of the position of the original corner.

Reference Pt. "A" - Found bent 1/2" rebar in line with fence line to North at centerline of East and West Townline Road. Found 1/2" rebar of unknown origin. Not in agreement with GLO proportional distances between A 13 and C 13 or CPC survey. Monument was established using improper procedures and is not utilized as B 13 - T15N - R3E in this survey. Reset large spike nail in position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

 $\frac{B\ 13}{24"}$ Replace pk nail with 2-3/4" Bay County brass cap on 5/8" x $\frac{B\ 13}{24"}$ rebar in mon. box.

24" rebar in mon. box.
S 46° E 39.22' to nail and tag in W. end 36" CMP.
S 66° W 59.43' to nail and tag in N. side U.P.
N 60° E 55.68' to nail and tag in SE. side 6" Pine.
N 68° W 39.89' to capped 3/8" rebar.

West 14.30' to Reference Pt. "A".

APPROVED LAND CORNER
P.A. 345 OF 1990 - Bay County

Michael MacDonaid P.S. County Representative OF MICALO
OF MICALO
OF MICALO
OF MICALO
MOVEAN
PHOTECSIONAL
SURVEYOR
O
NO.
39008

REVISED JAN., 1983

Signed by Craiz M. Ma Vac.
Surveyor's Michigan License No. 39088

Date 12/17/94