APPROVED LAND CORNER

Michael MacDonald P.S. County Representative

Bay County Remonumentation

Cutives w AEMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MAY 2 0 1997

For corners in Filing Requirement of Act 74 Mich P.A.		0 1997	
For corners in Filing Requirement of Act 74, Mich. P.A. 1970	MANAGEMENT COUNTY	18510 Ikc 30 4	
3. Miscellaneous S T R Property in Sec. S T R	OF DEEDS NICHAAN	98. 44 Oh	RECORDED
4. Lot No, Recorded Plat 5. Private Claims		amp & Fil	e Number

I, Paul M. Closek
In a field survey on October 28, 1995 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in Conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented. Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,

NOTE: Not more than 2 comers, all in the same town and range, may be recorded

A. Description of original monument and accessories and/or subsequent restoration:

Set post comm to T15/16N, H3/4E - 1822 - J. Wampler, D.S. Fnd post - ff, Parke, D.S. - April 1831 - S line, T16N, R3E. Fnd old corner - George Turner, C.S., 1908. (No call) - Edmands Engineering notes - 1959 - Janicke Sub., L. 8,

Fnd iron - L.C.R.C. - L. 1, P. 57 and <u>Recorded Survey</u> - L. 725, P. 52;

Fnd mon box - L.C.R.C. - L. 1, P. 111 and L. 1, P. 260.

No call - unrecorded survey by Edmands Engineering - May 28, 1970 and recorded survey, L. 840, p. 610.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Fnd 1/2" pipe in mon box at 4" below bit road surface, L.C.R.C. witnesses were to corners of headwalls that are gone. Remove 1/2" x 10" pipe and dig inside mon box, at 1.3' down fnd top of 5/8" smooth fron bar at 2.0' below bit find 5/8" fron to be in ctr of wood post and in agreement with top of 1/2" pipe location. Accepted 5/8" Iron in centerline of wood post as best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set Bay County Remonumentation mon (5/8" x 24" rebar with brass cap marked by 3/16" drill hole) by driving exist 5/8" iron down and raising mon box with 2 1/2" spacer at 2.3' N of const centerline of Linwood Road.

N 40° W 53.49' to Bay Co nail and tag (above PK) in SW face of P.P. NE 66.60' to Bay Co nail and tag (above PK) in W face of P.P. S 35° W 86.95' to Bay Co nall and tag (above PK) in E face of P.P. N 55° W 56.88' to SE cor of conc pad att to conc drive of Hse #12. S 45°E 31.39' to PS #25835 capped 3/8" rebar at 4" below surface

SW 110,55' to NE cor of conc drive at 27.5' \pm N of NE cor of att gar OF MC Hsc #13, Safe OF Michigan Burveyor's Michigan License No. 12/23/96 Paul M. Bearings are estimated & dist are hand chained -VOTE: CIOSTIK -OTE: See Bay County Remon Field Book Pg. 66 PROFESSIOHAL SUNVEYOR FORM APPROVED BY MICHIGAN STATE BOA No. PESSION REM 346