


## TRAY 2 C TEST

## REMON. COR. E-13, GARFIELD TWP. LAND CORNER RECORDATION CERTIFICATE

For corners in Bay	Filing Requi	rement of Act 74, Mic	h. P.A. 1970 		003	289
(County)	Located in:	Corner Code #				
1. Public Land Survey	T <u>16N R 3E</u> TR TR TR	E-13		REGISTE BAY COUN	Ocr 29	RE(
<ol> <li>Property Controlling S in Section S</li> <li>Miscellaneous S Property in Sec. S</li> </ol>	T R T R T R T R		Register of Deeds	R OF DEEDS	ile Number	RECORDED
4. Lot No, Recorded Plat _ 5. Private Claims			A B C	D E F		JKLI

I, JERRY JONES, in a field survey on MAY 21, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



- A. Description of original monument and accessories and/or subsequent restoration:
- E-13 Corner common to Section 32 and 33 on south town line

1831, R. Clark, set post, GLO notes

1967, Edmands Engineering breakdown of Sections 32 and 33, found 5/8" iron

1972, D. Whittier, PS #10070, LCRC, L-001, P-503, E-1, T15N-R3E, found 3/4" rod, 66.20' East of centerline of Garfield corner.

1977, L. McGinnis, PS #18999, rec. survey, L-822, P-538, set 1/2" bar

1980, E. Goss notes, reset capped iron

1983, D. Ledy, PS #21575, rec. survey, L-962, P-628, witnesses to cor.

1986, D. Ledy, PS #21575, rec survey, L-1047, P-283, found iron



WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- E-13 Corner common to Section 32 and 33 on south town line - no corner found

Set 5/8" rod and brass cap in mon box, per surveys by Edmands Engineering, L. McGinnis, E. Goss, D. Ledy and LCRC by D. Whittier

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- E-13 Corner common to Section 32 and 33 on south town line

Set 5/8" rod and brass cap stamped Bay County Remonumentation PS 19838, in mon box ber surveys by Edmands Engineering L. McGinnis, E. Go D. Ledy and LCRC D. Whittier; and is accepted as the best available evidence of the position of the accepted corner.

N 03 Deg E, 62.95', nail and B.C. tag in 15" Ash

N 50 Deg E, 74.14', nail in 10" Maple

S 60 Deg E, 46.14', nail and B.C. tag in fence post

S 60 Deg E, 113.92', nail and B.C. tag in power pole (113.3 to face rec in 1977)

S 15 Deg W, 23.40', nail and B.C. tag in 18" Ash stump

S 76 Deg E, 93.17', centerline USGS B.M. (10" + below road surface)

East, 66,20', E-1 Beaver Twp. (T15N-R3E)

Surveyor's Michigan License No. 19838

APPROVED LAND CORNER P.A. 345 OF 1990 - Bay County Date 13 June 56 MJM

Michael MacDonald P.S. County Representative

10/17/96 Date \_\_

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971 Revised May 14, 1971