

MAY 2 0 1997

REMON. COR. F-13, GARFIELD TWP. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in Bay	- 1	,)9 9 <u>0</u> 4
(County)	Located in:	Corner Code #)3 291
Public Land Survey	T <u>16N R 3E</u> T R T R T B	F-13	REGISTES BAY COUNT	REC OCT 29 L
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R R S T R S T R R R S T R R R R R R		Register of Deeds Stando & File No.	RECORDED
4. Lot No, Recorded 5. Private Claims	Plat			HIJKLM

I, <u>JERRY JONES</u>, in a field survey on <u>MAY 20</u>, 1996, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

2 3 4 1.0 6 18 16 7 8 20 21 23 9 10 3 ก 29 28 26 11 12 13

A. Description of original monument and accessories and/or subsequent restoration:

F-13 S 1/4 corner Section 33

1831, R. Clark, set post, GLO notes

1967, Edmands Engineering breakdown of Section 33, found 2" pipe

1977, Edmands Engineering, rec. survey, L-815, P-410, found 2" pipe

1977, L. McGinnis, PS #18999, rec. survey, L-822, P-538, found 2" pipe

1979, J. Schafer, PS #16409, rec. survey, L-881, P-267, found 2" pipe (survey wrong)

1980, E. Goss notes, found 2" pipe

1983, D. Ledy, PS #21575, rec. survey, L-962, P-628, found 3/8" bar

1983, D. Ledy, PS #21575, rec. survey, L-1047, P-283, found 3/8" bar



WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- F-13 S 1/4 corner Section 33

Found 3/8" rod per surveys by Edmands Engineering, L. McGinnis, J. Schafer, E. Goss and D. Ledy

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- F-13 S 1/4 corner Section 33

Found 3/8" rod per surveys by Edmands Engineering L. McGinnis, J. Schafer, E. Goss and D. Ledy replaced 3/8" rod with 5/8" rod and brass cap stamped Bay County Remonumentation PS 19838 in mon box, and is accepted as the best available evidence of the position of the accepted corner

\$ 5 Deg W, 34.11', nail in 15" Poplar

\$ 40 Deg W, 63.03', nail and plastic disc in 8" Pine

N 5 Deg E, 37.77', nail and plastic disc in pp type fence post

N 50 Deg E, 72.10', nail and plastic disc in pp type fence post

N 58 Deg W, 145.33', nail in power pole (Goss-1980 rec at 145.35', Edmands, 1977)

East, 52.48', 3/4" rod

East, 58.32', 3/8" rod

APPROVED LAND CORNER
P.A. 345 OF 1990 - Bay County
Date 13 June 94

MJM
Michael MacDonald P.S.
County Representative

Signed by

Date

0/12/96

Surveyor's Michigan License No. 19838

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
Revised May 14, 1971

Revised Jan., 1983