Lot No.

Private Claims _

Bay County Remonumentation

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74 Mich DA 1070

LIBER	003	PAGE	38
កេ >ក្រ	15. E. C.	"" "	
EAY CO	3. t	~)	:22

For comers in 1	994	i iiiig riequire	Y	יי יי	()		
Bay CC\\Covery		Located In:	Corner Code ##		EAY CO	22	(2)
Public Land St	urvey	T _T1ZNR _ R4E T _T17NR _ R4E T R T R	H-3				C0080ED
2. Property Contr in Section	rolling S S	T R				සු	1
3. Miscellaneous Property in Sec		T R		Register of	Deeds Stamp &	& File Nu	ımber

Craig W. McVean August 26 in a field survey on . 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Lawand/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	В	Ç	D	E	F	G	н	<u> </u>	K	L	M
2		6		5—		4—		3		Ţ,		_
3	<u> </u>	 	L	1_	<u> </u>	$oxed{oxed}$	L	Ĺ.,	L	_		
٠ 4	L	ļ_	L	8	L	 9	<u> </u>	T			1	2
5	_	_	L		L	<u> </u>	<u> </u>	L		L		
6	_	 18	<u> </u>	17	L	 16—	ļ_,	5—	_,	4-	1	3
7	_	1_		_			L	L				
В	L	 19	L.	 20—	<u>_</u> ;	 21—	2	22	2	3	2	4
9		1_	L	_	_			1_		Ĺ		
10	L	30	L	 29	ļ.,	 28—		27		6-		S
11	_	_	<u> </u>	_	_	_	L	<u></u>	_	Ĺ		
12	_	 31	1_	 32—		 33	1-3	 	<u> </u> _3	5	3	6
13	ļ	1	I	1		1	1	1		li		

Description of original monument and accessories and/or subsequent restoration:

H-3 Set post - J. Burt. 1843. Hemlock 14" N 41° E 16 Lks. Hemlock 4" S 81° W 27 Lks.

County Surveyor notes - G. Turner - 1907. Recorded Survey - L. 937, P. 156 - 1983.

1-3 Set post - J. Burt, 1843. B. Ash 7" N 34° E 14 Lks. Maple 6" S 60° W 13 Lks.

L.C.R.C. - L. 2, P. 101 - McGinnis - 1974 - pipe. Recorded Surveys - L. 1121, P. 821 - 1989; L. 719, P. 51 - 1973.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-3 Found 3/8" rebar per recorded survey with 3/4" pipe 1.5" below. Fits County Surveyor notes distance E and W. Monument accepted as the best available evidence of the position of the original corner. Accepted by Bay County Peer Review Group on 10-21-93.

J-3 Found 3/8" rebar with 3/4" pipe below per L.C.R.C. - L. 2, P. 101. Monument accepted as the best available evidence of the position of the original corner. Accepted by Bay County Peer Review Group on 11-4-93.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

H-3 Replaced 3/8" rebar with 2-3/4" Bay County brass cap on 5/8"

rebar in mon. box. N 3° W 34.42' to nail and tag in W face 10" Ash. N 45° E 158.40' to NW corner of house foundation. N 70° E 189.47' to SE corner garage foundation. S 12° E 25.51' to top centerline N end 12" CMP. NW 136.14' to NE corner of mobile home.

J-3 Remove 3/8" rebar. Drove pipe down. Set 2-3/4" Bay County brass cap on 5/8" x 24" rebar over pipe in mon. box. N 20° E 335.28' to SW corner house. N 34° W 73.56' to nall and tag in NE side 8" Maple.

N 25° W 83.23' to nail and tag in E side 10" Maple. N 50° E 33.93' to cap and nail in W side post.

	•		
Ω Ω Ω	011	, ,	
Signed by Crove W. Me	Ven	Date 12/20/93	
Surveyor's Michigan License No. 3908	38		.,