SECHON LAND CORNER RECORDATION CERTIFICATE INLAND TOWNSHIP Filing Requirement of Act 74, Mich. P.A. 1970 STATE OF MICHIGAN BENZIE COUNTY For corners in BENZIE COUNTY RECORDED Corner Code ## Located In: (County) 22 JAN 1999 3:04:07 PM T 26N B 13W 1. Public Land Survey MICHELLE R. GRAY T _____ R ___ REGISTER OF DEEDS T ____ R __ # PAGES DUE T_____R ____ 2. Property Controlling ___ T ____ R ·____ in Section ___ T .____ R ___ Miscellaneous Register of Deeds Stamp & File Number Property in Sec. __ , Recorded Plat _____ 5 Private Claims _{. 19} <u>9</u>8 John B. Smendzuik , in a field survey on December 1 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: J-7: 1837: GLO set post - Beech 14" N13°W 30 links and Beech 9" S12°W 4 links. Undated: Guy Langford, Survey Record II, page 50, cedar post set by original bearing tree. 1983: Bill Batzer, Certificate of Survey in Liber 1, Page 764, found 1" iron bar and witnessed it. 1983: BCRC found 1" iron bar. 1991 -1994: Various surveyors in area find and record 1" iron bar at corner. 1996-97: Michigan DNR section work, found 1" iron bar at Batzer position. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-7: 1998: Found 1"x 14" iron bar, 10" below existing grade, at distances shown on previous surveys. The Benzie County Peer Group accepted the iron bar as the best evidence of a locally accepted corner. Ratified by Peer Group In accordance with P.A. 345 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner; J-7: Pulled the iron bar and set a 3" diameter Benzie County Remonumentation Program concrete monument with a brass cap, 5" below grade of existing gravel road. 9" W. Birch S56°E 60.28' to found nail.

Gordon Bonney iron and cap South 32.95'.

Centerline of drive to north is West 12'. Centerline of drive to south is West 71'.

Signed by

Surveyor's Michigan License No.

9" W. Birch S12°W 33.47' to set nail and BCRP tag.

30895

Monument is in the centerline of St. John's Road.

Twin 8" and 9" Maple N58°E 71.93' to set nail and BCRP tag over found nail.

Date FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983