LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	
Benzie Located In: Corner Code #	
1. Public Land Survey	
2. Property Controlling STR	
in Section STR	
3. Miscellaneous S T R	
Troperty in Sec. S	Register of Deeds Stamp & File Numb
4. Lot No, Recorded Plat	
5. Private Claims	A B C D E F G R I J K L M
	3
I, Craig W. McVean_, in a field survey on May 5,19 98 do	4 7 12
hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner	5
points mentioned in lines 1 and 2 above were in conformance with regulations and	6 18 -17 -16 15 14 13
rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a	7
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were	8 -19 -20 -2122 -23 -24 -
in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered,	9
found as expressed below:	10 30 29 - 28 27 - 26 25
	11
	12-31-4-32-33-34-35-36-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	
A. Description of original monument and accessories and/or subsequent restoration	on:
K-3 -GLO - Inter. Platte Lake and set post - Alvin Burt - 1839 Pine 11" S34°E 20L	-LCRC - L.1, P. 35 - H. Bruning - 1974 FND. Iron.
Cedar 11″ S22°W 24L -Co. Bk., P. 158-159 – F. Haswell – 1896	NW. Cor. cottage S57°E 26.30'
Drove cedar post 3' deep from OBT's.	SW. Cor cottage S26°E 50.50′ NE. Cor cottage S39°W 48.90′
-Plat of Youkan Resort - J.A. Pettitt - 1906	-Rec. Survey L.1, P. 548&551 – H. Bruning - 1978
Planted Iron Monument.	1" Iron FND.
	-Rec. Survey L.1, P. 883 – R.M. Harris - 1986 -Rec. Survey L.2, P. 738 – B. Jenema - 1996
B. Description of corner evidence found and/or method applied in restoring or ree	stablishing corner:
K-3 - Corner common to Sec.'s 1,2,11&12, T26N,R15W. FND. leaning ½" Iron Rod in Bit. Rd. end. Removed ½"x15" Rebar and FND. 1 1/4" solid Iron Bar down 1.05'. At 1.35' down find that Iron Bar is driven into 1 1/4" I.D. Iron Pipe. Edge of Platte Lake is 18'± N. Monument accepted as the best available evidence of the position of the original corner.	
C. Description of monument for corner and accessories established to perpetuate le	ocating the position of the corner
K-3 - Raised 1 1/4" Iron Bar in Iron Pipe w/ 0.8' of 5/8" Rebar w/ 2" Alum. Cap in S50°W 25.23' to N&T in SE. Side 14" Cedar	Mon. Box.
S66°W 38.13' to NE. Cor. vinyl siding, Hse. # 7990-Addition	CRAIG W. \+
S81°E 22.19' to SE. Cor. vinyl siding, Hse. # 8006-Addition N75°W 74.33' to SE. Cor. Conc. Breakwall,	McVEAN + S
S24°E 50.60' to SW. Cor. vinyl siding, Hse. # 8006 at garage corner. (HB)	PROFESSIONAL & SURVEYOR
The state of the s	No.
	Resident State of the state of
	TOPE SSIONA
Signed by Oring M. Me Vern	Date 10/6/1998
Surveyor's Michigan License No. 39088	Date // 0/1770