LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		
Benzie Located In:	Corner Code #	
1. Public Land Survey 2. Property Controlling S T R INTERPOLATION	D - 11	Register of Deeds Stamp & File Numb,
4. Lot No , Recorded Plat		A B C D E F G H I J K L M
5. Private Claims		2 6 - 5 4 - 3 - 2 - 1 - 3 4 7 - 8 9 10 - 11 12 5 - 1 - 16 - 15 - 14 13
I, <u>Craig W. McVean</u> , in a field survey on <u>April 17,19</u> requirements of P.A. 74, Michigan P.A. of 1970, the corner points movere in conformance with regulations and rules therefore as required instructions of the United States Department of the Interior, Bureau of a Court of Law and /or that the corner points mentioned in lines 3, conformance with the rules of the Michigan Board of Land Surveyors established, re-established, monumented, recovered, found as express	entioned in lines 1 and 2 above in the current manual of survey of Land Management or by a decree 4 and 5 above were in or by a Decree of a Court of Law; sed below:	7
NOTE: Not more than 2 corners, all in the same town and certificate.	range, may be recorded on this	13
A. Description of original monument and accessories and/or subsequent restoration:		
D-11 - GLO - Set Qtr Post - J. Hunt - 1850 West corrected from corner of Sec.'s 28-29-32-33; 40.25 Ch. Birch 6" S41°E 36L Cedar 12" N26°W 16L Old Co. Survey Notes - Benzie Co. Reg of Deeds Pg.90 & 91 - F. S. Haswell - March 15, 1909 Survey for S-29 states for S1/4 S-30 "6 in Cedar Post drove from Original Witness" - Gourdie- Fraser & Assoc Field notes - Set Concrete Monument - 1976		
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:		
 D - 11 - ¼ Corner common to sections 29 and 32. Re-established corner at GLO distance from probable old GLO BT and in visible lines with blaze and bent over nails on 3 OBT's - origin unknown~ fits position of F. Haswell subdivision of S-29 and statement by Floyd Cooper, local resident since 1948. Position falls in mud hole, as remembered & pointed out by Mr. Cooper. Mr. Cooper remembers 4" pipe being in mud hole as corner monument. We measure West 95' ± , (82.5' GLO), to edge of Platte River. Monument accepted as a careful and faithful perpetuation of the position of the original corner. 		
- Reference Pt. 'A' - Found Gourdie-Fraser Concrete Monument per DeLaMater, N79°49'31"E 53.51'. Monument is close to SP position. Doesn't fit Topo. Call to River or Haswell's subdivision of S-29. Found 4 ½ "x 30" Iron Pipe & 6"x 1.5' long cedar post bottom, apparently being Haswell's, and it has been moved here along with Pipe, apparently from mud hole. Monument established using improper procedures and is not utilized as D-11 in this survey.		
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:		
D-11 - Set 4" DNR Alum. Cap on 1"x 6' long Galv. Iron Pipe in mud hole. Built ring of stone. Set Carsonite post * 12" Hemlock N28°E 19.08' (Drove nail and tag V 5" Hemlock N88°E 22.80' (Drove nail and tag * 14" Cedar S22°E 8.19' (Drove nail and tag in V 12" Cedar S40°W 49.99' (Drove nail and tag in V 9" Triple Maple S75°W 18.62' (Drove nail and V 9" Hemlock N25°W 30.98' (Drove nail and tag N20°W 10.6' (when raised) to fallen over 15" c * = Found old side nails - added new nail and tag V = Face blaze and scribe "XBT"	NE. 1.9'. Reset cedar post boin W. side) in N. side) SW'ly side) SE'ly side) tag in N. side) in W'ly side)	craig W. CRAIG W. McVEAN PROFESSIONAL SURVEYOR No. 39088
Signed by Cruy W Mallen		Date 9/29/1498
Surveyor's Michigan License No. 39088	FORM APPROVED BY MICHIGAN	STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
	· · · · · · · · · · · · · · · · · · ·	STATE OURSE OF PROFESSIONAL SUNVEYORS, JAN 28 1971