	BY THE BERRIEN COUNTY		Million of the second of the s		KEC01	ROED	
OFFICIAL	EY PEER GROUP AS THE CORNER UNDER MICHIGAN LTC AGE 345 OF 1990			Č.	KJ BUO LC	## A o o	
	13 Our	BERRIEN LAND CORN	COUNTY REMONUME ER RECORDATION C	ENTATION FRATE	My AUG 16	AM 9:28	
For corr	ners in	Filing Requi	ER RECORDATION C rement of Act 74, Mic	h. P.A. 1970	REGISTER OF	THE WAY F DEEDS	
Berrier	1 Loc	ated In:	Corner Code #		MALIA COOM!	T. MICHIGAN	
1. Publ	lic Land Survey	T <u>4S</u> R <u>17</u>	<u> </u>	_			
		T R		_			
	perty Controlling S	T R R T		<u> </u>	B/16/99	111#9898	A99
3. Misc	ection S cellaneous S perty in Sec. S	T R R	EC 2 8 1999	0	B/16/99	CORNER 111#9898 STATE REMON	\$7.00 A99 FEE \$2.00
4. Lot i	No, Recorded Plate Claims	at		_	Register of	Deeds Stamp & Fil	le Number
	/				A B C D	E F G H I	J K L M
				2	65-	4 3	21
				3			
do hereb	Strebs by state that under requirements	in a field surve of P.A. 74, Michigan	y on <u>17 June</u> , n P.A. of 1970, the come	, 199 <u>9</u> er points refore as		9 10	
required	d in lines 1 and 2 above were in the current manual of survey instance or by a de-	in conformance with structions of the Unite	regulations and rules ther ed States Department of the	refore as 🔌	1 1 1	16 15	14 13
mentione Land Sur	ed in lines 3, 4 and 5 above were rveyors or by a Decree of a Co	in conformance with	the rules of the Michigan	Board of 7			
	d, found as expressed below:  Not more than 2 corners, all in the	e same town and ran	na may be recorded	9			2324
110.2.	on this certificate.		ge, may be recorded	10		28 27 2	26 9 25
A. Des	cription of original monument	and accessories and	d/or subsequent restorat	13 ion: 12	1	33 34 3	3536
1830	WILLIAM BROOKFIELD, D.S SET 1/2 MILE POST 13" POPLAR S 76° W 14 LI 13" W OAK S 75° E 34 LIN	INKS		13	<u> </u>		<u> </u>
1965	BERRIEN COUNTY ROAD CO SW CORNER OF HOUSE NE 20" OAK N 30° E 89.7' PP N 40° W 151.3' 4" HICKORY EAST 42.5' IRON EAST 33.0'	OMMISSION (IRON	IN MONUMENT BOX)				
1972 & 1973	E.R. STEFAN (MONUMENT IRON PIPE EAST 33.0 TOP CENTER OF TEL. RISEF GUY WIRE ANCHOR N 80°	R N 60° E 66.4'					
1973	WIGHTMAN & ASSOCIATES IRON PIPE EAST 33.00° PK NAIL IN 12" BIRCH N 65 PK NAIL IN WOOD POST S	5° W 25.17'	IT BOX)				
1991	WIGHTMAN & ASSOCIATE: (IRON IN MONUMENT BOX) PK NAIL IN PP S 70° W 67. PK NAIL IN 12" POPLAR S E PK NAIL IN GUARD POST N PK NAIL IN GUARD POST N	0' 50° E 25.00' 45° E 28.8'			Internal	HILLING MICA	NAME OF THE PARTY
1993	ROGER STEPHENSON (IRON IN BOX) TEL. POLE N 70° E 67.5' 12" BIRCH N 60° W 25.1' 4" SASSAFRAS N 85° E 27	.0'			THE WALLES	# DOOTTOONULI	* SHIP
B. Des	cription of corner evidence fou	ind and/or method	applied in restoring or re	establishing c	orner:	WINININININININININININININININININININ	III.
FOUND !	5/8" ROD IN MONUMENT BOX	(					
C. Desc	cription of monument for corne	er and accessories e	stablished to perpetuate	locating the	position of th	e corner:	
	( 3' IRON PIPE WITH B.C.R.P.		NUMENT BOX.				
WIT TAG	G IN WOOD POST S 60° W 29 G IN WOOD POST WEST 21.50 G IN 4" SASSAFRAS EAST 26. G IN PP N 80° E 67.00'	יכ				•	
	ED AS A CAREFUL AND PAITH	HFUL PERPETUATIO	ON OF THE POSITION OF	F THE ORIGIN		<b>A</b>	a <i>c</i>
Signed by Surveyor	's Michigan License No. 264	69			Date <u>5</u>	Au6. 199	17
	*	LIBER	f4PAGE $f137$		AN STATE BOARD OF	REV	S, JAN. 28, 1971 D MAY 14,1975 ISED JAN., 1983 SED OCT., 1995