

	FEB 17 1994				
Fo	COMMISSION r corners in	Filing Require	R RECORDATION CERTIF	. 1970	111#3384 AT CURNER \$7.0 111#3384 AT
	Berrien (County)	Located In:	Corner Code ##	#	TATE BENON FEE \$2.0
1.	Public Land Survey	T R T R	<u>M6</u>	MANAGEN CEURI RICEN CEURI	EC 3 RECOR
	Property Controlling in Section Miscellaneous Property in Sec.	T R S T R S T R S T R		Register of Deeds	
	Fioperty in Sec.	J I N			
		ecorded Plat		— авсов	E F G H I J K L I
5. I		in a field survey on		2 6 5	9 10 11 12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, monumented, re-monumented, recovered, found as expressed below:					
NO	TE: Not more than 4 co on this certificate.	orners, all in the same town and	d range, may be recorded	11 32 31 32	-33 - 3435 - 36 -
A.	Description of original n	nonument and accessories and	or subsequent restoration:	10 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	····
M-6 J. H. Miller 1873 notes on file at Wightman and Associates, Inc. indicate a set stone at the east \$\frac{1}{4}\$ corner of section 13-5-19 as being 0.17 chains (11.22') south of the west \$\frac{1}{4}\$ corner of section 18. This jog has been referred to since then in old field notes. The only time it was monumented was in 1873, as the stone. The stone seems to have long since disappeared and historically since then, it appears that the well established west \$\frac{1}{4}\$ corner of section 18 has also been used for surveys in section 13. It also appears to have been used in establishing the center of section 13 and other corners on this quarter line since 1894. Also the 1873 Miller notes indicate there may have been a 20' discrepancy running the section line. Based on this evidence, the currently used west \$\frac{1}{4}\$ corner of section 18 is the location of the stone at the east \$\frac{1}{4}\$ corner of section 13 and therefore the west \$\frac{1}{4}\$ corner of section 18 and the east \$\frac{1}{4}\$ corner of section 13 are accepted as the same corner					
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:					
M-6 Found 3/4" pipe in Mon. Box. Accessories, PK in PP N 20° W 146.30', PK in PP N 20° E 145.80', PK in 8" Apple N 70° E 55.79', PK in PP S 30° W 61.31'.					
	٠,				
		nt for corner and accessories es pipe with brass plate in pla			
	and faithful perp Set Nail with ta Found Nail w/Tag	petuation of the position of g in PP N 13° E 145.90' in PP S 29° W 61.67' ag in 8" Twin Apple N 69° E g in 24" Stump S 55° E 39.16	Fithe original corner.	OF MICHIE	accepted as a carer
	1	$\gamma \nu$	* REGISTE	JOHN G. KAMER  NO SURVEYOR  NO. 27449  FO LANO SURVEYOR  TO LANO S	
Sia	ned by	lo, tome	Date	COLAND STATE	7-93

Signed by \_ Surveyor's Michigan License No. \_ 27449

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19
REVISED MAY 14, 19
REVISED JAN., 19

Date