SUPIVEY & REMONUMENTATION

RECORDED

FEB 1 7 1994

COMMISSION

| NEC | 28 | 2 | 17 | PM | '43 |
|------------|----|---|----|----|-----|
| 1151. | | - | | | |

Property in Sec.

5. Private Claims _

expressed below:

BERRIEN COUNTY REMONUMENTATION PROGRAM


| DEC 20 2 17 18 33 | LAND CORNER RECORDATION CERTIFICATE(2/28/93 | 111#5115 |
|---|---|----------|
| A 1 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 | Filing Requirement of Act 74, Mich. P.A. 1970 | CURNER |
| For corners in same of Visitioners | 12/28/93 | 111#5115 |

| | Berrientsteast Rosann | DUF IS Landbocated In: | Corner Code ## | STATE REMON FEE \$2. | 00 |
|----|--------------------------|-------------------------------------|----------------|---------------------------------------|----|
| | ALCOUNTY OF THE STATE | | <u>C</u> | | |
| 1. | Public Land Survey | T <u>8 s.</u> R <u>17 W.</u> T R | (C-9) F-9 | · | |
| | | T R | | | |
| | | T R | | | |
| 2. | Property Controlling | S | | | |
| | in Section | S T R | | | |
| 3. | Miscellaneous | S T R | | Register of Doods Stomp & File Number | |

Register of Deeds Stamp & File Number

| I, R.L. Harner , in a field survey on November 11, 1993 , |
|--|
| do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned |
| in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the |
| current manual of survey instructions of the United States Department of the Interior, Bureau of Land |
| Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 |
| above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a |
| Court of Law; established, re-established, monumented, re-monumented, recovered, found as |

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



Description of original monument and accessories and/or subsequent restoration:

| <u>C-9</u> . | |
|--|---------------|
| 3/4 [¶] pipe in mon. box - M.D.D. | T. March 1971 |
| 33" W. Cherry S. 55° W. 123.9 | O ft. |
| Cedar post N. 30° E. 22.68 f | t. |
| 4" steel fence post East 10.8 | 8 ft. |

___ , Recorded Plat __

5/8" iron D.L. Warren 1967

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/4" iron in mon. box

Found 5/8" iron

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 1" x 3' iron and brass cap in mon box N.W. corner of barn S. 02° E. 72.31 ft. N.E. corner of barn S. 60° E. 84.64 ft. Nail in P.P. J-111-71 S. 05° W. 99.65 ft. Nail in P.P. J-111-70 S. 45° W. 137.89 ft.

Set concrete monument with brass cap Nail in P.P. J-113-7 S. 88° W. 17.77 ft. Nail in 30" oak N. 45° E. 2.57 ft. Nail in 8" elm N. D5° W. 24.13 ft. S.E. corner of barn N. 40° E. 7.10 ft.

Signed by:

Date December 28, 1993

Surveyor's Michigan License No. ___

Fr. 72.136

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983