FEB 08-1999 -

SECTION

## BRANCH COUNTY REMONUMATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

F.,					
For corners in  BRANCH COUNTY  BUTLER TWP	. Located In:		Corner Co	de #	STATE OF MICHIGAN Branch County Recorded
1. Public Land Survey		R <u>5 W</u>	_D-3		11-04-1998 15:46:22
2. Property Controlling	T T S T	R R			Linda Lee Morrison-Mathews REGISTER OF DEEDS
in Section	T R			- Accepted my	Register of Deeds Stamp & File Number
3. Miscellaneous  Property in Sec.	TR SB	<del></del>		SURVEY PEER G CORNER UNDER M OF 1990 AT	THE BRANCH COUNTY IROUP AS THE OFFICIAL IICHIGAN PUBLIC ACT 345 A MEETING HELD ON
	I K		· · · · · · · · · · · · · · · · · · ·	- <u>E/</u>	R. Reed Co. Rep.
4. Lot No, Red				<b>L</b> .	-N.N.LLD ABCDEFGHIJKL
					- 1 2 3 4 3 3
I, <u>EDWARD W. REED</u> , in a field survey on <u>JULY 14</u> , 19 <u>98</u> do hereby stat that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the curren manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:				1 5 10 10 10 10 10 10 10 10 10 10 10 10 10	
NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.				10 30 29 28 27 26 25 11 12 31 32 33 34 35 36	
QUARTER CORNER COMMON TO SECTIONS 5 & 8					
A. Description of original mo	nument and acce	ssories and	or subsequen	t restoration:	
1825: R. CLARK, JR., D.S 1911: WW COX, DEPT CO GLASS & PIECES O 1977: E.R. REED, CO SUR RECORDED IN LCR	) Surveyor - : )F Brick :Veyor - Foun	SET GAS		•	4: REBAR IRON IN CENTER OF PIPE,
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:					
FOUND 1/2" IRON IN PIPE	AS DESCRIBED	AND FITT	ING WITNES	S OF LCRC # 2	06
C. Description of monu	ment for corner	and acces	sories estab	lished to perpeto	uate locating the position of the corner:
SET REMON CAP ON TOP	OF IRON, SET	CI-MONUI	MENT BOX 3	" BELOW GRAV	/EL ROAD SURFACE
AT NORTH SHOULDER OF 11.2' NORTH OF C/L OF H 48" DOUBLE OAK TEL PED CONC CULVERT SUPPORT 10" ASH CONC. CULVERT SUPPOR	ERRICKSVILLE S 27 E S 35 W S 11 E N 74 E	68.2' TO 61.9' TO 47.0' TO 48.6' TO	FACE TOP CENTE		EDWARD W. REED LAND SURVEYOR NO.
AND IS ACCEPTED AS BESOF THE ORIGINAL CORNE		EVIDENCE	OF THE PO	SITION	33985 LAND SURF
Signed by Edme	W. Ku			D	Pate_SEPTEMBER 9, 1998
EDWARD W,					
Surveyor's Michigan License No. 33985					Liber 00003 Page 0213