-----

**199**3

## BRANCH COUNTY REMONUMENTATION CORNER

## COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			•		4 K R 2312
	BRANCH (County)	Located In:	Corner Code ##		ON FOR ANCIN CONTROL OF THE OF MEDICAL CONTROL OF THE OF THE OTHER CONTROL OTHER CONTR
1.	Public Land Survey	T <u>6S</u> R <u>6W</u> T R T R T R	K-13	261	ARECURE DULLTY AN IO: 07
2.	Property Controlling in Section	S T R S T R			
3.	Miscellaneous Property in Sec.	S T R S T R		Register	of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_\_, Recorded Plat \_\_\_\_\_
5. Private Claims \_\_\_\_\_

L. Edward W. Reed in a field survey on November 30, 19, 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

3
4
7
8
9
10
11
12
3
6
19
20
21
22
23
24
9
10
30
29
28
27
26
25
11
12
31
32
33
34
35
36

A. Description of original monument and accessories and/or subsequent restoration:

SOUTHEAST CORNER OF SECTION 35, T6S, R6W, COLDWATER TWP.

1877: M. Knowles, Surveyor - set stone

1978: E.R. Reed, County Surveyor - found pointed stone,  $1\frac{1}{4}$ " iron pipe over stone, broken glass, orange flagging. Corner appears to have been recently recovered and used by David Boone, RLS # 18803 ( not recorded by Boone), Reed recorded corner in Land Corner Records #00231

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found  $l_4^{1}$  iron pipe over stone as described by E.R. Reed in Land Corner Record # 00231.

Set ½" x 18" rebar iron with ID cap in CI-monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Rebar iron as noted above.

N 18 W 55.3', center of 12" Walnut

N 72 W 92.5', center of 14" Walnut

S 64 E 42.3', center of telephone pedestal

East 15.8', C/L of north-south road.

And is accepted as a careful and faithful perpetuation

33985

Signed by the position of the original corner. Date November 30, 1993

Surveyor's Michigan License No.

\_\_\_\_\_

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

OF MICHIE

**EDWARD** 

W. REED

LAND SURVEYOR

NO.

O LAND SUR

EVISEU MAT 14, 1973 REVISED JAN., 1983