EURVEY & - TOTH MENTATION

JAN 2 3 1996 BRANCH COUNTY REMONUMENTATION CORNER

LAND	CORNER	RECORDAT	ON CERTIFICATE

For corners in COMMI	SSION Filing Requiren	nent of Act 74, Mich. P.A. 1	Liber UUUUJ Paae 0035		
MATTESON TOWNSHIP 1. Public Land Survey	T <u>6 S</u> R <u>8 W</u> T R	K8	STATE OF MICHIGAN Branch County Recorded		
	T R T R		09-28-1995 10:21:47		
in Section S 3. Miscellaneous S	S T R S T R S T R		Linda Lee Morrison-Nathews REGISTER OF DEEDS Register of Deeds Stamp & File Number		
•	S T R	,	MATTESON TWP.		
4. Lot No, Reco			A B C D E F G H J K L N		
			3 3 5 5 4 5 5 7 4 7 5 7 7 7 7 7 7 7 7 7 7 7		
EDWARD R. REED . in	a field survey on MAY 8	19 95	4 7 4 8 9 10 11 12		
do hereby certify that under require in lines 1 and 2 above were in concurrent manual of survey instruction Management or by a decree of a Conabove were in conformance with the Court of Law; established, re-established below:	ements of P.A. 74, Michigan P.A. of informance with regulations and it ins of the United States Department of Law and/or that the corner perules of the Michigan Board of Latablished, monumented, re-monagements.	1970, the corner points mentioned rules therefore as required in the ent of the Interior, Bureau of Land oints mentioned in lines 3, 4 and 5 and Surveyors or by a Decree of a numented, recovered, found as	6 18 17 16 15 14 13 14 13 15 14 13 15 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15		
NOTE: Not more than 4 corne on this certificate.	ers, all in the same town and	range, may be recorded	12 31 32 33 34 35 36		
A. Description of original monument and accessories and/or subsequent restoration: G.L.O.: Wm BROOKFIELD, D.S., 1826: "North between Secs.13 & 24. 40.00 Set qr. Sec. post, W Oak 10 N731/3W 25, Elm 6 N64E 20." H. CARY, DEP. CO. SURVEYOR, 1856: Survey of Secs. 23 & 24. Shows measurements to this corner but did not identify corner monument or witnesses. MSHD TRAVERSE NOTES OF 1969 ON LINE BETWEEN SECS. 23 & 24- Does not show a corner being located. G. E. ANDERSON, MSHD SURVEYOR, 1969: His section corner card states: "Did not find E4 of Sec. 23." R. E. SAYERS, SURVEYOR #7874: Assessor's Plat of SALEK FARM in 1985 references to East a post Sec. 23, but no corner information given on plat. B. Description of corner evidence found and/or method applied in restoring or rectablishing corner. Ran traverse between northeast corner and southeast corner of Section 23 = 5,306.08 feet; (MSHD 1969 fieldnotes = S 00° 09' 22" E 5,305.81 feet). Set 1/4-Section Corner at mid-distance of 2,653.04 feet. Corner is in west shoulder of Matteson Lake Road. Set 3/4" x 24" iron pipe, with a rebar with Remonumentation Cap, cemented in pipe, and placed C-I monument box over same. Top of monument box is one (1) foot below surface of ground. **Corner is in West Shoulder of Metrins Michigan Help on Metrins Help on Help o					
REMONUMENTATION CAR box. Top of box Lake Road, 9.2 feet pavement. In line with center S 22 E 87.0' to r S 23 E 88.3' to T S 57 E 45.6' to c N 72 E 49.2' to c	P ON ½"x18" rebar ir is one (1) foot belo twest of west edge or line of gravel road rear face of P. Pole. Telephone pedestal. Center, S end CMP culter, N end CMP culter.	on cemented in 3/4"x w surface of ground. f blacktop pavement (running East. vert. vert.	(24" iron pipe; in C-I monument In west shoulder of Matteson (nail and washer at west edge of		
And is accepted as	center of 40" Oak trees a cameful and faith	ful reestablishment o	of the R. REED LAND SURVEYOR NO.		
Signed by EDWARD R. RE Surveyor's Michigan License No.		DateMAY	M APPRILATE BY MICHIGANE STEE BOART DE LAND, SONVEYORS, JAN. 28, 197		
REVISED MAY 14, 1976 REVISED JAH., 198:					