SURVEY & REMONUMENTATION

FEB 0 3 1999

SECTION

BRANCH COUNTY REMONUMATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		STATE OF MICHIGAN Branch County
BRANCH COUNTY Located In:	Corner Code #	Recorded
1. Public Land Survey T_7 S_R_6 W TR		11-04-1998 15:47:21
TR TR		Linda Lee Morrison-Mathews REGISTER OF DEEDS
2. Property Controlling S T R in Section S		Register of Deeds Stamp & File Number
TRACCEPTED BY THE BRANCH COUNTY 3. Miscellaneous S SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345		
Property in Sec. S		
E.R.REED		
4. Lot No, Recorded Plat		A B C D E F G H I J K L P
		2 6 5 4 3 2 - 1 -
I, <u>EDWARD W. REED</u> , in a field survey on <u>JUL</u>	V 1/1 10 00 do harahy et	A - 7 - 8 - 9 - 10 - 11 - 12
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1		
manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /cr that the corner points mentioned in lines 3,		
4 and 5 above were in conformance with the rules of the Michi a Decree of a Court of Law; established, re-established, m	gan Board of Land Surveyors or	by 8 19 20 21 22 23 24 as
expressed below:		9 10 30 29 28 27 26 25
NOTE: Not more than 2 comers, all in the same town and rang on this certificate.	e, may be recorded	11 32 33 34 35 36
CORNER COMMON TO SECTIONS 5-6-7-8		
A. Description of original monument and accessories and/or subsequent restoration:		
1826: WM BROOKFIELD D. S CORNER SET		
1871: M. KNOWLES - D. S. FOUND STONE 1987: E. R. REED, CO. SURVEYOR - DUG FOR CORNER. PROBABLY REMOVED DURING ROAD BUILDING OPERATIONS. RESET CORNER (IRON PIPE IN CI -MONUMENT BOX) FROM OLD SCHOOL HOUSE FENCES. RECORDED IN LCRC # II-0096		
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:		
FOUND MONUMENT BOX AND IRON PIPE		
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:		
SET ½" X 18" REBAR IRON IN IRON PIPE WITH REMON CAP IN CAST IRON BOX		
C/L OF E- W ROAD	SOUTH 6.0' N 52 W 49.6'	W. REED LAND SURVEYOR
CENTER OF 14' ASH SOUTH WEST CORNER OF ORIGINAL		
BRICK CHURCH FACE OF TEL PED	N 50 E 93.5' N 51 W 43.3'	NO. 33985
FENCELINE RUNNING	SOUTHWEST 82.5'	D LAND SU
AND IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.		
Signed by Edwa W. Ruy		Date <u>SEPTEMBER 9, 1998</u>
EDWARD W, REED		Liber 00003 Page 0221
Surveyor's Michigan License No. 33985		LIDOY LILILILIA FOOD CONTROL SIEVEVORS JAN 28 197