APPROVED

Date <u>5-21-97</u> CALHOUN COUNTY REMONUMENTATION.

recovered, found as expressed below:

on this certificate.

CALHOUN COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN CALHOUN COUNTY RECORDED

23 HAY 97 4:30 P.H.

CALHOUN	Located In:	Corner Code #	ANNE B. NORLANDER CLERK - REGISTER OF DEEDS
(County) MARENGO TOWNSHIP 1. Public Land Survey	T <u>2S_R5W</u> TR TR	K-7	LIBER 1934 PAGE 953
Property Controlling in Section Miscellaneous Property in Sec.	TR S TR S TR S TR		Register of Deeds Stamp & File Number
4. Lot No, Records. Private Claims	rded Plat		A B C D E F G H I J K L I 2 6 5 4 3 2 1 1
under requirements of P.A. 74, Mic	chigan P.A. of 1970, the corner nd rules therefore as required in	VAY 8 , 19 97 do hereby sta points mentioned in lines 1 and 2 abov the current manual of survey instruct agement or by a decree of a Court of La	e were ions of 5

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

ORIGINAL SURVEY BY LUCIUS LYON, DEPUTY SURVEYOR, SET POST, W. OAK, 7", \$82½°W, 39 LINKS, B.OAK, 6", NORTH 47 LINKS

for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented,

J.M. GIFFORD, 1889, NOTED THAT THE CORNER HAD BEEN RESTORED AND PLACED BY B.F. WELLS, COUNTY SURVEYOR. SET TILLE IN SAME PLACE; HICKORY, 20", S61½°E, 92 LINKS, Y.OAK, 5", S61½°W, 92 LINKS.

1959, M.S.H.D. WITNESS CARD HAD A 11/2" IRON AND SET A MONUMENT BOX. 18" HICKORY, S67°E, 77.95"; 6" OAK, N64°E, 59.85"; 6" OAK, S26°W, 66.77"; STEEL CORNER POST, NORTH, 33.55'

MILTON DEKEYSER, P.S.#12019, IN LCRC DATED 9/20/73 AND RECORDED IN L.1027, P.63, STATED "FOUND NOTHING, ROAD RAISED 10". RESTROED USING PREVIOUS SURVEY BY J.H. ALDEN." SET 1/2" IRON. CORNER FENCE POST, N2°W, 33.65"; U.P. N65°E, 72.42"; U.P., S15°E, 118.67', GAS WARNING SIGN POST, S50°W, 111.69'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND A MONUMENT BOX WITH IRON. FOUND BROKEN HOLLOW TILE WITH ROCKS AROUND. UNSURE WHY DEKEYSER SAID THE ROAD HAD BEEN RAISED 10', DID NOT APPEAR TO HAVE BEEN RAISED. THERE IS A GAS PIPELINE RUNNING UNDER THE CORNER AND THE IRON REFERRED TO BY THE M.S.H.D. MAY HAVE BEEN DISTURBED THEN. CHECKED INTO THE REMAINING WITNESSES FROM PART "A" AND ACCEPTED THIS POSITION AS A CAREFUL AND FAITHFUL PERPETUATION OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET A BERNTSEN MONUMENT IN A MONUMENT BOX AND STAMPED CORNER INFORMATION AND LICENSE NUMBER IN BRASS CAP.

OF MICHAEL CAP.

WITNESSES TO BERNTSEN MONUMENT: NORTH 33.65 2" STEEL CORNER POST FACE OF N70°E 34.35' RAIL ROAD IRON POST FACE OF S50°E 59.50 **RAIL ROAD IRON POST** FACE OF RAIL ROAD TIE FENCE POST S80°W 53.45 **NAIL AND TAG** Ment MAY 21, 1997 Date . Signed by Surveyor's Michigan License No. 39079

SURVEY & REMONUMENTATION

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SUNVEYORS, JAN. 28, 1971

REVISED JAN., 1963 REVISED OCT., 1996

MICHAEL A

GROAT

PROFESSIONAL

SURVEYOR

No.

39079