LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

, or connect m			1							
Chippewa	Located In:	Corner Code #								
(County)										
1. Public Land Survey	T R T R T R									
2. Property Controlling in Section	S 5 T 41N R 5E S T R S T R	D2								
3. Miscellaneous	s r R									
Property in Sec.	S T R		, p,	egister (of Doc	de Sta	mn & F	ile Ni	umber	
4. Lot No. Re	corded Plat			egister	oi Dec	us Sta	прат	-		
5. Private Claims			1 A	B C	DE	F	G H	- I-	J K	L M
5. Trivate etains			2	<u></u>	.	-4-	┿			
<u>.</u>	02.40	0./2010	3 -	 	+		┵			
i, <u>Stephan J. Szyszkoski</u> , i	· · · · · · · · · · · · · · · · · · ·	9/2010 do hereby state	. 4 -	}_ _	- ģ	<u> </u>	- 1 ₀	-	-11	13
that under requirements of P.A.	74, Michigan P.A. of 1970, the co	rner points mentioned in lines 1 and	² s				++	_		
above were in conformance with	regulations and rules therefore as r	equired in the current manual of surve	y 51		.17_	 16	15		-14	13
		of Land Management or by a decree of and 5 above were in conformance with						\bot		
		ecree of a Court of Law; established			70_			止	_23	24
re-established, monumented, reco		serve of a court of Law, comments	- 1	i I	Ì		Ti		Ĭ	Ĩ
re established, monumented, reco	refeat, found as expressed serious		9							
NOTE: N		and may be recorded	10-	30	-29	28	1—27 1	1	-2 6	25
	ners, all in the same town and ra	ange, may be recorded	11	fff	+		++	十		
on this certificate.		×	12	<u> </u>	32	33	3 4		-35	36
			12	<u> </u>		l l		L		

A. Description of original monument and accessories and/or subsequent restoration:

(D2) Center of Section 5. Not established in the original survey. 1974 - Established by G.R.Gabel RLS. Set a 3"x4" alum. plate on a 1.5" dia. pipe 24" out of ground. Spruce 11" S13W 30.3', Birch 3" S42E 8.1', Birch 3" N19W 41.4'. Though Mr. Gabel does not state how he arrived at the position for the corner, calculations using his measurements of record prove that he established the position at the intersection of straight lines connecting opposite 1/4 corners. This corner was used in the further subdivision of Section 5 in 1974, 1986, and 2003 by Mr. Gabel and Eino Sainio RLS.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D2) Found the 1974 monument as described, in good condition, and in accord with Mr. Gabel's survey of Section 5. The 1974 witnesses were not recovered. Accepted the corner as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D2) Fd. 3"x4" alum. plate on 1.5" Iron Pipe. Set measuring nail with MDNR tag in the side of:

6" B.Spruce NO6E 12.9'

mrkd "CS BT"

4" Balsam S77E 16.95'

do

12" B.Spruce S16E 40.15' 4" W.Birch S70W 46.0'

do do

33986

Bearings are magnetic.

Surveyor's Michigan License No.

Signed by

Date

07/27/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

OF M/C

YSZKOSKI

STEPHAN J

LAND SURVEYOR

AND