

# LAND CORNER RECORDATION CERTIFICATE

**FILING REQUIREMENT OF ACT 74, MICH. P.A. 1970**  
Chippewa Co. 1 Corner

FOR CORNERS OF--:	LOCATED IN--:	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. _____	N. S., R. _____ E. W.	Meander Corner North of K-9 Called K-9A
2. PROPERTY CONTROLLING IN SECTION <u>23</u> , T. <u>41</u>	N. S., R. <u>7</u> E. W.	
3. MISCELLANEOUS PROPERTY IN SECTION _____ , T. _____	N. S., R. _____ E. W.	
4. LOT NO. _____ , RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND FILING NUMBER

I, Billy D. Buckler, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on 7-23, 1975, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

**K-9A** Meander Corner between Sections 23-24, on South side of a Point of Land on Lake Huron.  
Set by John Mullett, D.S. in 1845. Original notes indicate an 8" Cedar for corner.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

**K-9A** Found a dead Cedar Stub, 8" in diameter, with old blazes. Stub is weathered, has some callous overgrowth on the blazes. Believe this to be the original corner tree.


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

**K-9A** Placed no new monument, at this time. Marked new bearings:  
9" Cedar, marked (M.C. 23/24 NBT), N30°W, 7.9' & 9" Cedar, marked (M.C. 23/24 NBT), S58°W, 29.2'.

SIGNED BY Billy D. Buckler  
BILLY D. BUCKLER

DATE 5-5-81

SURVEYOR'S MICHIGAN REGISTRATION NO. 8887



FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ CHIEF OF SURVEY PARTY

DATE \_\_\_\_\_

APPROVED AND SIGNED BY \_\_\_\_\_ MICHIGAN REGISTERED LAND SURVEYOR

DATE \_\_\_\_\_

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_