SURYEY &

Chippewa County Remonumentation Corner

RECEIVED FOR RECORD CHIPPEWA COUNTY STATE OF HICHIGAN

MAR 0 9 1994

LAND CORNER RECORDATION CERTIFICATE

93 DEC 29 PM 2: 51

Fo	r corners in	がいる Filing Requir	ement of Act 74, Mich. P.	A. 1970
	Chippewa	Located In:	Corner Code ##	J. Roger Malith
	(County)		3311131 3333	REGISTER OF DEEDS
1.	Public Land Survey	T <u>44N R 2E</u> T <u>43N R 2E</u> T <u>44N R 3E</u> T <u>43N R 3E</u>	M-13\ M-1 Township A-13 Corner A-1 /	
2.	Property Controlling in Section	S T R S T R		
3.	Miscellaneous Property in Sec.	S T R S T R	***************************************	Register of Deeds Stamp & File Number
		, Recorded Plat		A B C D E F G H I J K L

I, William T. Karr in a field survey on December 15 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

on this certificate.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded A. Description of original monument and accessories and/or subsequent restoration: (M-13) Township corner - Southeast Corner Section 36 (T44N-R2E), Southwest Corner Section 31 (T44N-R3E), Northeast Corner Section 1 (T43N-R2E) and Northwest Corner STREET

Original Notes: Austin Burt, September 1840.

Section 6 (T43N-R3E.

Elm 18 N19°E 31 links N87°W Elm 16 16 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

 $m_{\mu \eta \eta \eta \eta \eta \eta}$ This corner is being re-established as part of the Chippewa County Remonumentation Program.

Found no evidence of the original corner. Found remains of rotted post, 15" pipe and a newer concrete monument. All three are called for in a Harry Goodwin survey L.S. 5434, dated October 1976. Goodwin set the concrete monument. This evidence is significantly out of position based on other monumentation and GLO calls in the area. Distance from the Southwest corner of Section 36 to the South & corner of Section 36 is 2650' today which was also noted by Kimberly-Clark in 1963 (GLO is 2640). Both of these corners can be traced back to original evidence. If you extend this line East 2640' (GLO is 2640) and establish the Township Corner, the found Goodwin corner is 229'± West and 23'± South. (Continued on back)

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (M-13) Corner is a 3/4" x 8' rod with "Chippewa County" stamped aluminum cap. Area is heavy, open marsh with standing water.

Witnesses:

Meander Corner 31/6 (R3E) S89°17'38"E 432.96' N89°17'38"W South & Corner Section 36 2640.00' Concrete Monument S85°00'49"W 230.887 North Fiberglass Post 4.00' Fiberglass Post 4.00'

Signed by . 27450



Surveyor's Michigan License No. 27450

Surveyor's Michigan License No. 27450

NOTE: Bearings are compass bearings corrected for declination. REVISED MAY 14, 1975 REVISED JAN., 1983

Distances are to a nail in side of witness objects unless noted.