## LAND CORNER RECORDATION CERTIFICATE

## FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

Chippewa Co.

3 Corners

	•	•		
	OR CORNERS OF -:		CORNER CODE NUMBER	
1.	PUBLIC LAND SURVEY	т. <b>45</b> х., R. <u>1</u>	E. M-10, K-10	
2.	PROPERTY CONTROLL- ING IN SECTION-2	5 . ,T45 \$., R1	E. 74	
3.	MISCELLANEOUS PROPERTY IN SECTION	, T	E. W.	
4.	LOT NO, RE	ECORDED PLAT		
5.	PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
1	David B. Babbit	t do harab	re contifue that readon magazinements	of P.A. 74, Michigan P.A. of 1970,
re an Be an	econies points incitioned in established, monumented, in drules therefore as required areau of Land Management and 5 above were, in a field su	re-monumented, recovered or d in the current manual of so or by a decree of a court of l rvey on	r restored as expressed below an urvey instructions of the United law. Furthermore, that the corne, 19, found, recovered, re-	, 19, established, d in conformance with regulations States Department of the Interior, er points mentioned in lines 3, 4 stored, established or re-established tration for Land Surveyors or, by a
	0 East 1/4 Corner of N60 <sup>0</sup> W, 22 lks. (	Co. Survevor F. Brow	Post. OBT'S: Sugar 20 n about 1925. New Cedar	, S34 <sup>0</sup> W, 35 lks. & Maple 18, r Post South of old one. .2 ' & 12" Maple, S10 <sup>0</sup> E, 42'.
K-1	0 West 1/4 Corner of Fir 8, N80 <sup>0</sup> W, 22	of Section 25. Wood 1ks.	Post. OBT'S: Hemlock	12, S45 <sup>O</sup> E, 13 lks. and
14	South 1/16 Corner	on East side of Sec	ction 25. Not prev. set	t.
B. M-10	. Description of corner evidence found and/or method applied in restoring or re-establishing corner: .O Found 1" Iron Bar with the original Sugar B.T. alive and standing (now 36"), S34 <sup>0</sup> W, 23.1' Brown's N.E. N.B.T. is alive and standing. Brown's S.E. N.B.T. is down and badly rotted.			
K-10	Set from remains of Hemlock stump presumed to be the S.E. O.B.T. County Surveyors records dated 1904 to 1907 indicate both O.B.T'S. were in place at that time. The land was being occupied and fenced at that time also. This corner falls in line with a faint road grade west and the N. 1/16 corner position falls in an old road grade north from that point and in line with an old fence west.			
14 <sub>C.</sub>	Corner set M.P.O. Description of monument	L. between East 1/4 for corner and accessories est	corner and S.E. section ablished to perpetuate locating the	corner of section 25.
M-1(	) 1" Re-Bar. Beari 6" R. Maple, Sout	ngs: 10" R. Maple', h, 43.7' & 36" H. Ma	N81 <sup>O</sup> E, 29.3' & 4" R. Ma uple, (Original), S34 <sup>O</sup> W,	ple, N30 <sup>o</sup> W, 13.95′ & 23.1′.
K-10	D.N.R. Monument. 5" Cedar, S47 <sup>0</sup> W,	Bearings: 8" W. Bi 22.7' & 6" Cedar, SI	irch, N23 <sup>0</sup> W, 29.8' & 8" 16 <sup>0</sup> W, 26.2'.	Cedar, S55 <sup>0</sup> E, 4.9' &
14	D.N.R. Monument. 6" Spruce, S33 <sup>0</sup> E,	Bearings: 8" W. Bi 29.2' & 9" Aspen, S	irch, N8 <sup>0</sup> W, 10.2' & 7" A 519 <sup>0</sup> W, 11.3'.	spen, N80 <sup>0</sup> E, 23.0' &
SI	GNED BY a win	P B. Babbitt	2 	84
SU	David B. Ba RVEYOR'S MICHIGAN RI	•		(SEAL)