LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	Corners in	Locat	led in:	Corner Code ##		-									
2.	Public Land Survey Property Controlling In Section Miscellaneous Property in Sec.	T T T S T S T S T	45N R 1E R R R R R R R R R R R R R R R R R	E8	F	iegister	of (Peed	s Sta	mp	& F	ile f	Yum	ber	
5.	Private Claims			tember 15, 1993 , 19		2 3	8-	C I	D E	<u></u>	G	H 1		K	-12-
do i in li curi Mar abo Cou	neraby certify that under rec nes 1 and 2 above were it rent manual of survey instri nagement or by a decree of we were in conformance wi	quirements of P.A. n conformance will uctions of the Unit a Courl of Law and th the rules of the F	74, Michigan P.A. th regulations at ted States Depai /or that the corn Michigan Board i	of 1970, the corner points men not rules therefore as required riment of the Interior, Bureau er points mentioned in lines 3, of Land Surveyors or by a Dec monumented, recovered, for	ntioned d in the of Land 4 and 5	5 6 7 8	-18	20	•	16-	-1:	5	-14- 	+	-13- -13- -24- -24-
NO.	TE: Not more than 4 c on this certificate.	orners, all in the	same town s	nd range, may be recorde	d	11 12	31-	32		33		-	-26- 	-	36
A. (E8	Description of original () Quarter corner common	monument and a to Sections 20-2	accessories an 21. Corner est	d/or subsequent restoratio tablished in 1845 by James	en: H. Mullei		lla	· ·	A sug	gar	6 in	 ı. ir	 1 dia		tor

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

iron pipe capped with a yellow plastic cap stamped "Mich DNR LS 33986".

quarter section corner." Original notes show section corners 40.00 ch. north and south. Found no subsequent record.

(E8) Original corner tree not recovered. The corner falls in a N-S lane separating two cleared fields. Mathanial Armstrong and Bernard Doll, both life-time residents of this area and land owners in sections 20 and 21, both admitted to me in July 1993 that they have never seen nor heard of a monument at this corner, nor know of it's existence. Two old N-S fence lines run roughly parallel to the lane on the east and west, neither run in a straight line but meander and jog. Mr. Armstrong told me that the lane was one of the first Co. roads to be built in this area, that it existed before 1906, and was constructed prior to 15 Mile Rd. It once extended southerly to the SM corner of Sec. 21, a perpetuated original corner. Mr. Armstrong stated that the fence lines bordering the lane were moved in the 1960's to accomposate school bus passage and that the location of the fences, to his knowledge, were positions of convenience, and that "nobody worried if the fences were on the line or not". Although the road to the north and the remains of the road to the south are not perfectly straight, the general trend clearly indicates that the road approximates a line between the section corners having an angle point at the quarter corner location. The road bed itself is the oldest recovered evidence of the position of the original corner and is accepted as such. (Continued under Part A. above...)

(Part B continued from below)... I reestablished the corner in the center of the old road bed, as best as could be determined, and equidistant between perpetuated original section corners 2637.60' north and south. At the position for the corner, I placed a 1'x36"

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

(E8) Set 1° pipe with plastic cap. Set measuring nails with tags in the following accessories: wood fence post \$75W 9.9 wood fence post \$400 16.6" wood fence post N30N 27.5' 6" Spruce N60E 40.6" Bearings are magnetic.



Surveyor's Michigan License No.