LAND CORNER RECORDATION CERTIFICATE Fiting Requirement of Act 74, Mich. P.A. 1970

For corners in Chippena			
(County)	Located In:	Corner Code ##	
1. Public Land Survey	T <u>45N</u> R <u>1E</u> T R T R	69	
Property Controlling in Section Miscellaneous Property in Sec.	S T R S T R S T R S T R	10	Register of Deeds Stamp & File Number
4. Lot No, R 5. Private Claims	lecorded Plat		A B C D E F G H J K L
do hereby certify that under recin lines 1 and 2 above were in current manual of survey instru- Management or by a decree of a above were in conformance with Court of Law; established, respressed below:	I0 Jai, in a field survey on 69 Selutirements of P.A. 74, Michigan P.A. conformance with regulations at the United States Depais Court of Law and/or that the corn hithe rules of the Michigan Board e-established, monumented, reporters, all in the same town a	. of 1970, the corner points ment not rules therafore as required riment of the Interior, Bureau of er points mentioned in lines 3, 4 of Land Surveyors or by a Decre monumented, recovered, four	in the in

A. Description of original monument and accessories and/or subsequent restoration:

(69) Corner common to sections 21-22-27-28. Original corner established in 1845 by James H. Mullett with accessories as follows: Aspen 12 S80W 18, Aspen 8 N25E 20. County Surveyor notes by F.H. Brown, 1926 show a symbol in the field notes for this corner but no other explanatory notes. Brown shows 5272' west to a "U.S. Cor.". Found no subsequent record.

(10-Sec. 21) South 1/16 corner beetween sections 20-21. Corner not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(69) Recovered a wood post at the southerly terminus of a N-S fence line. Bernard Doll, a long-time area resident, told me in July 1993 that he placed the post around 1950 at its present location, being the position of an old post which he had found, and that he understood the post to represent the position of the corner. Did not recover the original post or accessories and noted no other evidence of prior monumentation. Distances north and west from the post are 5248' (5280'R) and 5279' (5273'A) respectively, to monumentad corners. Brown's notes show, and my measurements confirm that there appears to be a 3-4 chain discrepancy with the record in the distance east to section corner 22-23-26-27, rendering that corner nearly useless in evaluating the position of 69. I accepted the post as the best available evidence of the position of the original corner and placed, at it's position, a 1"x36" iron pipe capped with a 4" dia. cast aluminum MONR tablet, appropriately stamped.

(10-Sec.21) Found no evidence of previous monumentation. Established the corner midway and on a straight line between restored government corners 1318.80° north and south. The corner position falls in the east side of an old M-S road bed, now brushed over. At the position for the corner, I placed a 1°I.0.x36° iron pipe capped with a 4° dia. cast aluminum MDNR tablet, appropriately stamped.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(69) Set 1" pipe with 4" MONR cap.
Blazed and set measuring nails with tags
in the following new bearing trees:
5" Elm S63W 20.8"
4" Balsam M39W 24.9"
5" Elm M17W 21.3"
Fence post M08E 12.1"
Bearings magnetic. The N8Ts are not scribed.



(10) Set 1° pipe with 4° MONR cap.
Blazed, scribed, and set measuring mails with tags in the following bearing trees:

6° Cedar \$37E 73.6' "\$1/16 8T" 3° Balsam \$30E 47.0' "\$1/16 8T" 4° Balsam \$40 35.3' "\$1/16 8T" \$1/16 8T" \$1/16 8T" \$1/16 8T" \$1/16 8T"

Rearings magnetic.

Signed by Style J. Sychol. Date 1-25-44

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND EURYEYDRS, JAN. 28.