LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		, initial trademantal and trademantal trademantal and trademan	
_	Chippewa (County)	Located In:	Corner Code ##
1.	Public Land Survey	T45N A _ LE	_E7
		T R T R	
		T R	
2.		\$ T R	
	in Section	\$ T R	

3. Miscellaneous

expressed below

Property in Sec.

Register of Deeds Stamp & File Number

4.	Lot No	Recorded Plat
_		

J. Stephan J. Szyszkoski , in a field survey on July 21, 1993 . 19	_ ,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention	
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in	the
current manual of survey instructions of the United States Department of the Interior, Bureau of Li	and
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 ar	id 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree	of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found	85

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(£7) Corner common to Sections 16-17-20-21. Original corner established in 1845 by James H. Mullett. Original BTs: Fir 8 S43£ 11, Cedar 10 M43W 20. Field notes of former Chippewa Co. Surveyor F.H.Brown, dated July, 1903 show "An original U.S. Cor" here and the following accessories (which are F.H. Browns possibly ca. 1920's.): HW 41' fence cor., N34£ 48.5' Elm 8, S58 1/2W 59.5' Elm 6, SE 40.5' fence cor., SE 37' small boulder, north 32' E-W range of fence, West 29' range of fence north, West 26.5' range of fence south, East 30' range of fence south, East 74' range of west side school bldg., North 64' range of south side school bldg., NS2E to SW cor school, found no subsequent record.

8. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

(E7) original post and accessories not recovered. Corner falls in the paved surface of 15 Mile Rd. in a fill. Remonumented the corner at the original position as determined from the remains of the 1926 accessories: the old school building, now abandoned and decrepit, and the small boulder, apparently undisturbed. The fences all appear to have been constructed subsequent to Brown's record and do not check. Fences to the NE and SE are non-existent. A shed was added to the south side of the school after Brown witnessed the corner. At the position for the corner, I drove a 1"x36" iron pipe capped with a yellow plastic cap stamped "NICH DNR LS 33986". From the corner monumented, I found a PX nail in the center of 15 mile road surfacing 1.35" north and 0.2" west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

[E7] 1° iron pipe with plastic cap Distances to the following bearing objects are to nails set in plastic caps stamped LS 33142. Bearings magnetic. Power pole N20N 56.4° corner fnc post (fnc S&W) 538N 58.8° corner fnc post (fnc N&E) N70E L31.45° post marking telephone riser \$26E 52.55°



1-25-94

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 19