LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970 Two Corners.

FOR CORNERS OF -:	LOCATED IN-:	CORNER CODE NUMBER	
I. PUBLIC LAND SURVEY	T S., R E.		:
2. PROPERTY CONTROLL- ING IN SECTION –	10 ,T. 45 %, R. 7 W.	1-Sec.10 2-Sec.10	
	N. N. E. S., R. W.	Į.	
	ECORDED PLAT		
5. PRIVATE CLAIMS			
			REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentione field survey on restored as expressed belo of survey instructions of the court of law. Furtherm 19	ed in lines 1 and 2 above (ide 4-15-19.74), established wand in conformance with regarded United States Department of core, that the corner points many, found, recovered, restored,	entified with circles on indexed, re-established, monumente red, re-established, monumente relations and rules therefore as f the Interior, Bureau of Land I mentioned in lines 3,4 and 5 a established or re-established	P.A.74, Michigan P.A. of 1970, code diagram – over) were, in a d, re-monumented, recovered or required in the current manual Management or by a decree of a above were, in a field survey on as expressed below and in conservence, by a Decree of a Court of
A. Description of original:	monument and accessories and	V or subsequent restoration:	
1-Sec.10 West 1/16 corner, on Northside, Section 10.			
2-Sec.10 East 1	/16 corner, on Northsid	de. Section 10.	
1-Sec.10 Corner	ridence found and/or method applaced midway bet. Secondary bet. Secondary bet.	c. Cor. to West and ‡ C	for. to East.
l-Sec.10 Buried Bearing	1" x 36" pipe in road. gs are: 10" Tamarack,	N15°W, 54.1' and 12"	ting the position of the corner; Cedar, S10 W, 64.51
2-Sec.10 Buried Bearing	$\frac{1}{2}$ " x 12" iron in road. gs are: 14" W. Pine,	S22°E, 43.4' and 8" 0	edar, N48°W, 50.0°
SURVEYOR'S MICHIGAN F	Suckler REGISTRATION NO. 8887		887
FOR STATE AND UNITED			LAND SUN
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	
APPROVED AND SIGNED I	BY. MICHIGAN HEGISTERLO LA	AND SURVEYOR DATE:	(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO.

FOR NO. WANTED

FOR NO.