LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. PA.1970

	v2p,	JOH 2 00,	z corners.	
	FOR CORNERS OF-:	LOCATED IN-:	CORNER CODE NUMBER	
٠	1. PUBLIC LAND SURVEY	т. <u>49</u> ж., к. <u>6</u> 1	H-5	
	2. PROPERTY CONTROLL-15 ING IN SECTION	_ ,T. 49 N. R. 6	2-Sec.15	
	3. MISCELLANEOUS PROPERTY IN SECTION		E	
	LOT NO, RECORDED PLAT			
	5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND
	I, Billy D. Buckler	, do hereby	certify that under requirements	of P.A. 74, Michigan P.A. of 1970
i e	re-established, monumented, re- and rules therefore as required : Bureau of Land Management or and 5 above were, in a field surv	monumented, recovered or in the current manual of sur by a decree of a court of la ey on	restored as expressed below and every instructions of the United 5 w. Furthermore, that the corner, 19, found, recovered, res	5-23, 19 77, established in conformance with regulation States Department of the Interior points mentioned in lines 3, established or re-established tration for Land Surveyors or, by a
H-5	A. Description of original monu 1/4 Cor. bet. Sec Tam. 6", S22°W, 4		ells Burt. D.S. in 1849	. Bearings were:
	.15 East 1/16 Corner			
H-5	Corner restored by East thru an original	y extending a strait inal W. Pine Line Tr	plied in restoring or re-establishing line from original series at 2,452.87 (recono original Tam. beari	ction corner 9-10-15-16 rd = 37-12 cha.) and
2-Sec	.15 Placed corner on 1 proportionate dist	line bet. 1/4 corner tance East of the 1/	to West and Heander C /4 Corner.	orner to East and at
	2. Description of monument for 1 m pipe with 4 m alum.		blished to perpetuate locating the	position of the corner:
H-5	New Bearings: 6"	Cedar, South, 4.4	and 10" Gedar, S88	E, 16.7'.
2-Sec.	15 Bearings: 6" Ceds Corner lies in Wes	r, N68 ⁰ W, 8.8° an	d 6 ^m Cedar, N11 ⁰ E, 2 f four Maples.	2.51.
				ARE OF WICE
S	IGNED BY ST	ly & Buckl	DATE 7-8-81	BILLY OF BUCKLER LAND SURVEYOR
	BILLY D. Buckl URVEYOR'S MICHIGAN REG	9 0007		687 K