			EK KECUKI												
For corners in	Fil	ing Requi	rement of A	ct 74, M	ich. P.A.	1970									
					1										
Chippewa	Located In:	Cor	ner Code #		ĺ										
(County)															
1. Public Land Survey	- 50N c	₹ ⁷ ₩	H12												
1. Public Land Survey	· · · · · · · · · · · · · · · · · · ·	₹		_											
		₹		_											
		₹													
2. Property Controlling	S 34 T 50N F	₹ 7W	8												
in Section		₹													
3. Miscellaneous	S FF	₹			1										
Property in Sec.	S F	₹		_			Rec	ister	of De	eds S	tamp	& Fil	a Ni	ımher	
					L		1108	10.0.	0. 5.		· · · · · · ·			2111001	-
4 Lot No.	ada d Diak														
4. Lot No, Reco	rded Plat		•			, ,	4 В	С	D I	F	G H	I	J	кL	1
5. Filvate Claims						1	·		Ī				Ĭ		
. 5		Tun 20	2007			2	-6		- 5	4 i	ال ا		- 2 —	 1	
Stanhan I Szyczkocki		Jun 20				3	\dashv				1			 	
Stephan J. Szyszkoski	, in a field survey or	ገ	, 19 do	hereby st	ate that unde	er 4	− Ż	\dashv	- ġ	— ģ—	10	+	-1,1—	12	_
requirements of P.A. 74, Michiga conformance with regulations and	an P.A. of 1970, the col	rner points m	enuonea in iines	5 1 and ∠	above were i	n el	-	_	-		1			+-+	
United States Department of the	Interior, Bureau of Land	Management	or by a decree o	of a Court	of Law and /d	or 6 .	18		-17	16	115	4	 -1 4	13	
that the corner points mentioned	I in lines 3, 4 and 5 abov	ve were in cor	nformance with the	the rules of	the Michiga	n 7				_	$\perp \perp$		\perp		
Board of Land Surveyors or by recovered, found as expressed by		or Law, esc	abiished, re-est	abished,	monumented	3, 8			 -20—	 —21—	\perp_{22}		 -23	1 24	
						-	Ĭ		Ĭ	Ī					
NOTE: Not more than 2 con	ners, all in the same to	wn and rang	ge, may be reco	orded		9						\top	1		
on this certificate.						10	—30 I	+	-2 ² 9	28	27.	+	-26—	25	-
						11	-+	\rightarrow	+		++		+	++	_
						12	31	_	3 2	3 3	-	-	-35	36	
						13						\bot		<u>1_1</u>	
A. Description of original mo	nument and accesso	ories and/or	subsequent re	estoration	n:										
(8-Sec. 34) West 1/16 corner					·										
						•									
B. Description of corner evi	dence found and/or r	method app	lied in restoring	g or rees	tablishing c	orner:									
(H12) Established the corner in the Betsy River and was n position for H12. The WITNE 10.95 [sic] East" but the s (8-Sec. 34) Established the Mest.	ot monumented. Est SS CORNER falls at tamped arrow points	ablished a the top of west to th	WITNESS CORNE bank on the e e corner posi	ER to H12 east side ition.	on the E of the ri	:-W 1/4 [ver. T	line The m	e of nonum	the S ent c	ection ap is	, 10.6 incori	o' E ectl	ast ly st	of the amped	3
C. Description of monument	for corner and acces	ssories estal	blished to perp	petuate id	cating the	position	of th	ne co	rner:						
12" Spruce S43E 20.6' 12" Spruce N24W 22.2'	corner o H12. Set kd "WC BT" do do	MDNR cap. 4" J.Pine N 7" J.Pine S 14" J.Pine 7" R.Pine E Fd. 1" pipe	343W 31.78' \$36E 25.27' SAST 31.85' \$ \$17E 15.37'	g nails i #rkd "Wi (n: 1/16 BT" fo do do										
7" twin Spruce NO2W 27.75' Bearings are magnetic. Dist		_	e magnetic. To nail with t		2 r0										
nail with tag.	ances are to	nees are t	o naii mith i	ıay.			/	,							
V7.1		1.1				2/	8	100	1					•	
Signed by	- July	2200			Date	01	<u> </u>	/	<u> </u>				-		_
Surveyor's Michigan License	No. <u>U</u>	3398	6												