## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	
Clare Located In:	Corner Code #
1. Public Land Survey T 17N R 5W	E9
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	Register of Deeds Stamp & File Num
4. Lot No, Recorded Plat	
5. Private Claims	2 6 5 4 3 - 2 - 1
I, Craig W. McVean , in a field survey on July 26 , 20 00 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on 12 31 32 33 34 35 36 this certificate.	
A. Description of original monument and accessories and/or subsequent restoration:	
<ul> <li>E9 - 1837, GLO set post, H. Nicholson. Hemlock 15" S 37° W 8 Links Hemlock 9" S 18° E 21 Links</li> <li>County Survey Record, Book 6, p. 29 - A.D. Johnson Elm 6" S 40° E 52.5 Links S. Maple 6" S 56.5° E 68 Links</li> <li>- 1981, K.J. Ostling, LCRC, L.1 P.655, set DNR monument from A.D. Johnson wit. PK nail in 18" Maple S 55° E 45.7' PK nail in 7" Beech N 54° E 46.4'</li> </ul>	-LCRC L.1, P.642 - P.B. Lapham 1981-Fd. DNR Mon. South 23.88 DNR Post S75°E 45.67' - 18" Maple N50°E 45.22' - 10" Beech N5°E 34.33 - 20" Beech -Unrec. Sur Lapham & Assoc. #813471-1981 - DNR MonMears Eng. Notes-1994-Fd. Spike Set 5/8" Rod/Cap
<ul> <li>B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:</li> <li>E9 - Section corner common to Sec. 20,21,28 &amp; 29 - Found 1" x 18" iron pipe with core of broken DNR aluminum cap inside. SE CSR Wit. in place. CL of E-W gravel rd. is 3'+ N. Old fences N &amp; S. Broken DNR Mon. accepted as the best available evidence of the position of the original corner.</li> </ul>	
-Reference Pt Fd. 5/8" capped iron #18223 - N1°58'E 11.74' of E9. Capped iron apparently set without regard to record DNR Mon. and is not utilized as E9 in this survey.	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	
Replace DNR Mon. w/ 2" DNR Alum. Cap on 5/8" x 34" Rebar in Mon. Box - Down 0.5' N5°E 34.42' to nail and tag in W side of 14" Beech (PBL) N42°E 45.41' to nail and tag in W side of 12" Beech (PBL) S35°E 29.38' to nail and tag in NW side of 6" Oak Clump South 33.00' to Fd. bent ½" capped iron rod #9433 & set Orange Carsonite Post w/ Tag S56°E 45.57' to Fd. Nail in N. side 26" S. Maple (CSR, KJO, PBL) North 3.55' to Wilcox 1/2" Rebar - Rd. Survey Control Pt. N1°58'E 11.74' to Ref. Pt.  2" DNR Mon. used & accepted in place of Clare Co. Remon. Mon.  39088	
Signed by Orine W. M. Ven	Date /0//8/2000

Surveyor's Michigan Lieense No. 39088