RECEIVI FV # 140-96 96 NOV 14 PH 4: 14

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in CLARE Corner Code # Located In: (County) T 18NR **3**W 1. Public Land Survey R R 2. Property Controlling Ŧ in Section R 3. Miscellaneous R Property in Sec. _, Recorded Plat 4. Lot No.

REGISTER OF DEEDS CLARE COUNTY DONNA M. CARR

Register of Deeds Stamp & File Number

10-24-82 MUELLER, (132) L.2, PG. 765 WIT.-FOUND 1/2" IN PVM'T AS RECORDED.

3 4

6

A

10 1

12

| 5. Private Claims | | | | |
|-------------------|------------------------|--------|---------------|-------------------|
| | | | | |
| L MARK R. ROBISON | . in a field survey on | AUGUST | 19 96 do here | by state that und |

requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

1856 CANNON WIT.-CEDAR 20" \$63°W 30 LKS. TAMARAC 21" N47 1/2°E 35 LKS.

5-7-09 JOHNSON, C.S.R. L.4, PG. 159 WIT.-SAME WITNESSES AS G.L.O.

NO DATE C.S.R. L.5, PG. 46 WIT.-SAME WITNESSES AS G.L.O I-5 TO I-4 = 40.30 1/2

NO DATE C.S.R. L.5, PG.47 WIT.-I-5 TO I-4 = 39.75

S

Sones and/or subsequent restoration:

10-19-71 LAPHAM, L.C.R.C. #13 WIT
WIT.-SET CAPPED 1/2" RE-ROD.
16' NORTH OF ROAD INTERSECTION
MEASURED FROM NORTH FROM E 1/4 CORNER
& DOUBLED OVER FENCES
N30"W, 91.0"— POWER POLE.
S70"W, 37.4" — FENCE COR.

21-76 LAPHAM, L.C.R.C. #240 f.-FOUND 1/2" IRON. N30°E, 46.69' - POWER POLE. S85°E, 32.74' - FENCE COR. N45°W, 44.27' - TELE. POLE.

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" IRON IN INTERSECTION CENTER-LINES ASPHALT PVM'T IN 6' FILL AREA. MEAS. NORTH 2613.72' TO 1-4 (FOUND 1/8 LINE FENCES AT MID POINT) MEAS. NORTH 2622.60' I-4 TO 1-3 (FOUND 1/8 LINE FENCES AT MID POINT) MEAS. SOUTH 2 TO 1-6 (FOUND 1/8 LINE FENCES AT 1304') THE MEASUREMENTS TO THE SOUTH DO NOT VALIDATE I-6 MEAS. SOUTH 2589.16' (FOUND 1/8 LINE FENCES AT 1282') ACCEPTED FOUND 1/2" IRON AS CORNER. SOUTH 2692.38'

See dossier for detailed report.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 5/8"x36' RE-ROD WITH 3" CLARE COUNTY MONUMENT CAP.
ACCEPTED AS BEST AVAILABLE EVIDENCE OF THE ACCEPTED POSITION OF THE CORNER.

WITNESSES.

N43°E, 46.74' - NAIL & TAG IN POWER POLE (OBT). S55°W, 77.32' - NAIL & TAG IN 5" CEDAR.

EAST, 97.56' - NAIL & TAG IN ELM.
N44'W, 46.48' - NAIL & TAG IN COR. FENCE POST. DO TE OF APPROVED LAND CORNER

P.A. 945 of 1990

Clare County

Chairman fluid 1.

Deis__

27458

THE OF MICHION MARK R. ROBISON PROFESSIONAL

SURVEYOR No.

Date 10-1-96

Surveyor's Michigan License No.

OFESSION POST AP POFESSIONA

APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 197 REVISED MAY 14,197 REVISED JAN., 198 REVISED OCT., 199