LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. PA 1970
Clare County Remonumentation

2/3/2003	Signed by: Caully Milliam Date: 1
acap Down 0.5' I cap Down 0.5' CRAIG W. MCVEAN PROFESSIONAL SURVEYOR No. 39088	C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: S0° 22/29" W 5.48' to Fd. 3/" iron rod – "Amended Monument" North 33' to set blue carsonite post w/ loc. tag N89°E 8.64' to Fd. 1/2" I.D. Iron pipe N20°E 43.89' to Fd. Nail in W. side 13" Oak N60°E 57.69' to set N & T in NW side Tw. 8" Oak N42°E 42.88' to Fd. N & T in SE side U.P. S51°E 41.38' to set N & T in NE side U.P. (PBL) S28°W 72.87' to Fd. Nail in SE side Q0" Oak (PBL) N89° 58'10"W 754.13' Grid Dist. (754.38' GLO) to G13, T21N, R3W
bilishing corner: of CL 'T' gravel rd. intersection per LCRC, Rec. CL of 'T' intersection but reject pipe as corner. Upon of the Standard Line but at the correct closing ended North to Standard Line for true intersection L. of E-W Gravel Rd. CL. of Gravel Rd. S is 7'± E.	B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: G1 - Closing Sec. Corner common to Sec. 4 & 5 - Fd. ¾" Iron rod 5' ± S and 7' ± W. of CL 'T' gravel rd. intersection per LCRC, Rec. Surveys and Plat. Also found a ½" iron pipe N56' 55' E 10.38' of ¾" iron rod in CL of 'T' intersection but reject pipe as corner. Upon Remonumentation of Standard Line the ¾" iron rod was found to be 5.48' south of the Standard Line but at the correct closing distance East of 'G13', T21N, R3W. Held ¾" iron rod for line from 'G2' and extended North to Standard Line for true intersection for closing corner and set 4" DOC (DNR) Brass Cap on 1" x 36" Galv. Iron. in CL. of E-W Gravel Rd. CL. of Gravel Rd. S is 7'± E.
trestoration: "Highland Oaks Sub." – L. 15 of Plats, p. 4 – P. B. Lapham – 1974 Rec. Sur. – L. 1, p. 720 – J. W. Sedgman – 1974; L. 2, p. 137 – J. W. Sedgman – 1976; L. 2, p. 296 – J. W. Sedgman – 1977; L. 2, p. 856 – R. L. Merry – 1984 - (All survey reference to LCRC #123-73)	A. Description of original monument and accessories and/or subsequent restoration: G1 - GLO - Intersect N. Bdy. 11.43 CH East of post at cor. of - "Highland Oaks Sub." – Sec. 33 & 34, T21N, R3W on 2 nd correction line and set post - Rec. Sur. – L. 1, p. 720 W. Pine 9" S24 ½"W 11 L. Adair - 1856 W. Pine 9" S24 ½"W 11 L. Adair - 1856 Aspen 8" S76°E 32 L. U. Sedgman – 1977; - LCRC #123-73 (L. 1, p. 245) – P. B. Lapham - 1973 Fd. ½" Sucker Rod; S60°W 93.30' – 10" Tri Oak; S45°W 68.10' – 14" R. Oak; S45°E 38.0' - pp
10	NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.
3 4	I. <u>Craig W. McVean</u> , in a field survey on <u>Oct. 27</u> , 20 <u>03</u> do hereby state that under requirements of PA 74, Michlgan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:
2	5. Private Claims:
Register of Deeds Stamp & File Number	iy Controlling ion aneous y in Section
į	Clare Located In Corner Code # (County) 1. Public Land Survey T 20N R 3W G1