

MAR 2.9 2000

		a critical at the principality
Located In:	Corner Code #	17 AUG 99 12:32 P.M.
T 25N R 4W T R T R		SANDRA MOORE REGISTER OF DEEDS
T R T R T R		Register of Deeds Stamp & File Numbe
4 PAG	that under requirements of P.A.	1 A B C D E F G H I J K L I 2 6 5 4 3 2 1 3 4 7 8 9 10 11 11 12 12
	Located In: T 25N R 4W T R T R T R T R T R T R T R T R T R T R	T 25N R 4W D-7 T R T R T R T R T R T R T R T R T R

Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered,

10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O - 1852 Addison P. Brewer, DS

Mon. - Set W. Oak Post

found as expressed below:

16" Y. Pine N58°E 7 lks.

14" Y. Pine S36°W 42 lks.

May 1879 Co. Surveyor's Book

Mon - not given

Wit:

16" Y. Pine S56 1/2"W 52 lks

L2, P. 192 LCRC Sept 1978

K. J. Ostling #10068

Mon- Fd. 2" Pipe 3' South of Centerline E-W Road Replaced with DNR Mon.

Wit: Nail & tag 14" W. Oak \$63°W 59.8

Nail & tag 8" J. Pine S08°E 56.25 Cedar Post Southeast 40.00

L. 234, P. 509 April 1985 M. MacDonald # 22438 Mon - Fd. DNR Mon.

Wit: Fence Corner SW 46.6 Face U. Pole NW 44.7

DNR Cedar Post SE 39.5 to nail & tag

1930's M. Schaaf Mon - Iron

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Standard DNR; found DNR Cedar Post S26°E 39.5 (recorded as 40); found face of UP N28°W 44.3 (recorded as 44.7); found fence corner post S52°W 46.0 (recorded as 46.6); found nail in E. side 21" W. Oak S63°W 59.2 (recorded as 59.8)

Accepted DNR monument as the best available evidence of the position of the Original Corner. Left DNR Monument in place. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

OF MOS.

Mon - Standard DNR Monument.

Wit: DNR Cedar Post S26°E 39.5

Face of UP N28°W 44.3

Face of Fence corner post S52°W 46.0

Nail in E. side 21" W. Oak S63°W 59.2

Carsonite Post N54°E 54'±

CRAWFORD COUNTY PEER GROUP APPROVAL

> Oprison E. Marvin E. Myers, P.S. **County Surveyor**

SATE OF MICHIQ MARVIN E. **MYERS** JOERS 316 PROFESSIONAL Surveyor's Michigan License No. 31600

Date June 9, 1999