Carl	SUFINE WINTERTON
1000	MAR 0.8 100A
	2.88

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	r '
STATE OF	F MICHIGAN
CONTRACTOR	THUMBAN
COUNTY	HARLEVOIX
RECEIVED	TOR RECORD
	COLUMN CONTRACTOR

2.4mm

For	corners	in
-----	---------	----

			•				<i>1</i> 33	ULL	10	P	H I	# 2	6		
_	Charlevoix	Located In:	Corner Code ##								•		_		
	(County)				(2	Care		an t	تور	2	300			
1. Public Land Survey		T <u>32N</u> R <u>4W</u> T R	B-1		\		REGI	iste	R OF	D	EEO	=4_)S	••		
		T R													
2.	Property Controlling	S T R	ſ				•								
	in Section	S T R	i												
3.		S T R		Posi	ster o	. n	aada		(o. E:	11. F	.l	ha.		
٠.	Property in Sec.	S T R	i i	negi				5 31a	inh c	—	116 1		Dei		_
4.	Lot No ,	Recorded Plat			A	В	СВ) E	F (G f	H 1	ائ ا	ĸ	L	i
5.	Private Claims				Ä	-	Ť	Ī		Ħ	ĤΤ	\exists	Ť	Ť	-
					2 -	В	 5-	+-	4-1	<u>—</u> з	} ─┤	ģ.		- i -	-
					3	 	} - 	-	+-+	Н	┝╌┧		_		_
					4	ļ	- 8⋅	_	. _	1	<u>. </u>	1 11.	\perp	i2-	_
1.	Wayne E. Boss	, in a field survey on Septem	mber 22 19 93		5	L			$oldsymbol{\perp}$	\Box	ot				
		equirements of P.A. 74, Michigan P.A.			6										
		in conformance with regulations an			9 1	8— 	'i'	"	16	_';	i	14-		13- 	
		ructions of the United States Depart				 	1-1		+-1		\vdash	_	\dashv	+	-
Ma	anagement or by a decree of	f a Court of Law and/or that the corne	er points mentioned in lines 3, 4.	ania o	81 4	`~	l ob	- 1	o. I		. 1			64.	

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. John Mullett May 1840 Set 1/4 Sec post 1. Sugar 14. N.71°E.30.

2. Beech 8. N.63°W.36.

on this certificate.

Restored 1/4 cor. per E.A. Robinson May 14, 1906. Set 1/4 Sec Post from G.L.O. witnesses. Still in and OK. Marcus Schaaf set 2" pipe for 1/4 cor. (Carl Roser determined Schaaf cor. to be erroneous and 34.9' South of actual cor.)

Restored 1/4 Cor. 2/7/86 by Carl Roser PS. DNR Mon. set.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded

Found DNR Mon, which was corner restored by Carl Roser, PS, and whose method of restoration is recorded in Liber 2, Page 201, and reads as follows:

- B-1 Restored S 1/4 corner Sec. 31 (T33N-R4W), N 1/4 corner Sec. 6 (T2N-R4W), per E.A. Robinson survey of N. line of Sec. 6, dated May 14, 1906; see Hudson (32-4), Bk. C-296, pg. 10, at Jury Room in courthouse. Robinson's notes say "at 21.25 ch. W. of 1/4 Corner small spring, rivulet that soaks into ground on his random between fd. 1/4 Corner from Govt. B.T.'s" (spring was on line extended W. bet. NE & N 1/4 Cor. of Sec. 6 (32-4). We recovered this spring, very definite, to restore 1/4 Cor. & pro-rated to E. A. Robinson bet. fd. NE & NW of Sec. 6. Fits his var. of the compass reasonable.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-1	Found DNR N	lon. & Cedar F	ost per Liber	2, Page 201, Charlevoix County Records, Charlevoix County,				
	Michigan, and is accepted as a careful and faithful reestablishment of the position of the original corner.							
	5" Maple	N20°E	15.1′	Fd. Blaze & Tags				
	6" Maple	S88°E	35.5′	Fd. Blaze & Tags				
	6" Itonwood	S48°E	25.1′	Fd. Blaze & Tags				
	4″ Maple	N60°W	38.5′	Fd. Blaze & Tags				
	2" Schaaf pipe	(drove flush)						
		N67°11′E	89,3′					

Signed by \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	We From	Date	December 9, 1993	
Surveyor's Michigan License No.	, , , , , , , , , , , , , , , , , , , ,			