Approved By Delta Company Land Survey Remonumentation Peer Group Under Act 345 Of

	1990 On DEC 18, 287 1999
LAND CORNER RECORDATION CERTIFICATE <u>Vido-</u> Filing Requirement of Act 74, Mich. P.A. 1970 <i>Act</i>	ng Chairman
For corners in	
	7, L 2 2000
RECONDED_ 2~ic?	O'CLOCK PM
	9 PAGE 202
TR	Mass C. Thran
2. Property Controlling S TR	TY MI REG. OF DEEDS
in Section ST_R	
3. Miscellaneous S T R Property in Sec. S T R	
Register	of Deeds Stamp & File Number
I-01 (NW COR SEC 2)	,
4. Lot No, Recorded Plat 5. Private Claims	DEFGHIJKL
2 - 6	-54321-
3	
I, M.P. DAVIS , in a field survey on NOVEMBER 19 99 do hereby state that under 4 requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in	- 8 10 11 12
conformance with regulations and rules therefore as required in the current manual of survey instructions of the	
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan	-17
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:	20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	
on this certificate.	-29 - 28 - 27 - 26 - 25
11	
12 - 31	-3'23'33'43'53'6-
A. Description of original monument and accessories and/or subsequent restoration: -01 [NW COR SEC 2] A.MERRYWEATHER, D.S1848-WOOD POST (SUGAR 08" N22°E 14 LINKS) (SUGAR 08" S67°W 48 BILLY D. BUCKLER-1961-FOUND IN PLACE A 3/4" (RON BAR AT ROA INTERSECTION, FROM WHICH (FENCE COF N42°W 47.4') (FENCE CORNER S40°E 40.9') RECORDED IN LIBER 3 OF LCR'S PAGE 213. GARY KOEPKE-1987-FOUND 3/8" IRON PIN IN ROAD INTERSECTION, ID FROM BUCKLER BT'S AND NOTED NEW BT 57.63') (APPLE 09" S40°E 41.64') (PP S40°W 46.24') (FENCE POST N25°E 66.93') RECORDED INLIBER 5 OF I	RNER S36°W 44.2")(FENCE CORNER ''S (MAPLE 28" N55°E
;	SURVEY &
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	EMONUMENTATION
-01 [NW COR SEC 2] FOUND IN PLACE A 1"(OD)!.P. AS DESCRIBED IN L.3 PG. 213 AND L.5 PG. 307 OF LCR'S. NO EVIDENCE OF 3/8" IRON PIN AS MENTIONED IN BOTH LCR'S. MAPLE BT AND PP BT ARE STILL VIABLE.	FEB 1 0 2000
ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.	SECTION
(
→	
	· .
C. Description of monument for corner and accessories established to perpetuate locating the position of the co	rner:
C. Description of monument for corner and accessories established to perpetuate locating the position of the co01 SET, INSIDE OF EXISTING MONUMENT, A 5/8" X 18" REBAR W/A 3-1/4" ALUM CAP STAMPED TO ID THE CORNE YIELD SIGN POST MAPLE 28"(OLD BT) SURVEY MONUMENT SIGN POST PP (OLD BT) N27*W N55*E S36*E S40*W 44.85' 57.63' 35.05' 46.24'	
-01 SET, INSIDE OF EXISTING MONUMENT, A 5/8" X 18" REBAR W/A 3-1/4" ALUM CAP STAMPED TO ID THE CORNE YIELD SIGN POST MAPLE 28"(OLD BT) SURVEY MONUMENT SIGN POST PP (OLD BT) N27"W N55"E S36"E S40"W	
-01 SET, INSIDE OF EXISTING MONUMENT, A 5/8" X 18" REBAR W/A 3-1/4" ALUM CAP STAMPED TO ID THE CORNE YIELD SIGN POST MAPLE 28"(OLD BT) SURVEY MONUMENT SIGN POST PP (OLD BT) N27"W N55"E S36"E S40"W	
-01 SET, INSIDE OF EXISTING MONUMENT, A 5/8" X 18" REBAR W/A 3-1/4" ALUM CAP STAMPED TO ID THE CORNE YIELD SIGN POST MAPLE 28"(OLD BT) SURVEY MONUMENT SIGN POST PP (OLD BT) N27"W N55"E S36"E S40"W	ER POSITION.
-01 SET, INSIDE OF EXISTING MONUMENT, A 5/8" X 18" REBAR W/A 3-1/4" ALUM CAP STAMPED TO ID THE CORNE YIELD SIGN POST MAPLE 28"(OLD BT) SURVEY MONUMENT SIGN POST PP (OLD BT) N27"W N55"E S36"E S40"W 44.85' 57.63' 35.05' 46.24'	G, UNLESS OTHERWISE NOTED.