

FFR 2 2 1996

COMMISSION

Approved By Delta County Land Survey Remonumentation Peer Group Under Act 345 Of

			/
LAND	CORNER	RECORDATION	CERTIFICATE_

P.A. QI 1990	On <u>/0/26</u>	199 <i>5</i>
TE MULTE	11 10	
ATE ZALVILA	Jehne	en
N.V.	Chairman	

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in DELTA Located In: Corner Code ## (County) T 38 N R 24 W Public Land Survey R T38N R 23W a 9:00 o'clock AM in Liber 8 Walter R T **Property Controlling** in Section S T R Miscellaneous R S T Register of Deeds Stamp & File Number Property in Sec. S , Recorded Plat 4. Lot No. (TAME AS A-8 & A-9 T38N R23N) M-8 [E1/4 COR S.24] M-9 [NE COR S.25] 3 SEPTEMBER in a field survey on do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 я above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below: 10 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 11 on this certificate. 12 Description of original monument and accessories and/or subsequent restoration: M-8 [E1/4 COR S.24] JOHN BURT, D.S. - 1845 - CORNER TRZE, HEMLOCK 03"- (HEMLOCK 09"-S55"N-14 LINKS) NO RECORD EVIDENCE OF SUBSEQUENT CORNER RECOVERY OR MONUMENTATION

- M-9 [NE COR S.25] JOHN BURT, D.S. 1845 WOOD POST (CEDAR 06" S54°W-18 LINKS) (CEDAR 06"-N35°W-15 LINKS)

 A.MERRYWEATHER, D.S. 1847 WOOD POST (TAMARACK 10"-N30°E-10 LINKS) (CEDAR 09"-S40°E-18 LINKS) from survey of T38N R23W

 JOSEPH E. GINGRASS-1933-IDENTIFIED FROM ORIGINALS-SET NEW STAKE-NO NEW WIT'S SHOWN IN THE RECORDS
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- M-8 [E1/4 COR S.24]NO ORIGINAL CORNER EVIDENCE FOUND & NO IDENTIFIABLE INDICATION OF SUBSEQUENT CORNER RESTORATION FOUND. REESTABLISHED CORNER POSITION AT MIDPOINT BETWEEN SECTION CORNERS 1/2 MILE NORTH & SOUTH.
- M-9 [NE COR S.25] FOUND IN PLACE A SQ'D. WOOD POST AS SET FROM THE ORIGINALS BY J.E. GINGRASS IN 1933, FROM WHICH A TAMARACK STUMP BEARS N.30°E-6.60'. (A. MERYWEATEER D.S.-1847). THE BT STUMP IS BADLY DETERIORATED & NO IDENTIFIABLE MARKS ARE VISIBLE. DISTANCE EAST TO THE 1/4 COMMON TO SECTION 19/30 T38N R23N CHECKS WELL WITH THE RECORDS OF GINGRASS. ACCEPTED EXISTING WOOD POST AS BEING A CAREFUL & FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.



C.	Description of	monument for	r corner and	accessories	established	to perpetuate	locating the	e position	of the corn	ier:
	_									

M-8 SET BERNTSEN AINB30 ALUMN MONUMENT W/A 31/4" CAP STAMPED TO ID THE CORNER POSITION.
CEDAR 7" CEDAR 8" CEDAR 8" CEDAR 7" CEDAR 7" CEDAR 8" CEDAR

CEDAR 7" CEDAR 8" CEDAR 8" CEDAR 7" SURVEY MONUMENT SIGN POST N47"N N35"E S47"E S54"W WEST 12/80' 17.60' 1.52' 7.37' 2.35' (TO FACE)

M-9 REPLACED WOOD POST W/A BERNTSEN AINB3D ALUMN MONUMENT W/A 31/4" CAP STAMPED TO ID THE CORNER POSITION.

 CEDAR 8"
 CEDAR 7"
 CEDAR 7"
 CEDAR 7"
 SURVEY MONUMENT SIGN POST

 N21'E
 S75°E
 S06°E
 S76°N
 NORTH

 15.48'
 17.33'
 12.42'
 14.85'
 1.59' (TO FACE)

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC - DISTANCES ARE TO A NAIL IN THE CENTER OF THE OBJECT UNLESS NOTED OTHERWISE