REMONUMENTATION

AUG 2 0 1996

F

Privatę Claims

Land Survey Remonumentation Peer Group Under Act 345 Of

Approved By Delta County

P.A. Of 1990 On Lune 27, 1996 Phy Dela

COMMISSION	Filing Requ	irement of Act 74, Mich. P	P.A. 1970	Chairman	
DELTA	Located In:	Corner Code ##			
(County)					

Public Land Survey 38 JR __ 23_W 28 June 1996 Records R 9:00 A.M. R 10 **Property Controlling** S R ___ R in Section S Deita County, Michigan Miscellaneous _ T __ R Register of Deeds Stamp & File Number Property in Sec. _ T _ _ , Recorded Plat . Lot No

, in a field survey on M.P. DAVIS MARCH do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

B-3 [N1/4 COR S7] B-5 [N1/4 COR S18]

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 10 11 12
- A. Description of original monument and accessories and/or subsequent restoration:
 - B-3 IN1/4 COR S.71 WOOD POST A.MERRYWEATHER, D.S. 1847 (TAMARACK 12"-N70°E-16 LINKS) (CEDAR 12"-S68°W-33 LINKS) M.S.McNABB-1947-FD. IN PLACE WOOD POST SCRIBED "1/4" AT JCT. OF FENCE LINES W.& S. (CEDAR 14"-N32"W-28'(CEDAR 3"-S51"E-35.75) M.DAVIS-1979-FOUND IN PLACE BOTH OF MCNABB'S 1947 BTS BOTH STILL GREEN. REMONUMENTED CORNER POSITION W/A 1" X 36" I.P. FROM WHICE A NEW BT - W.BIRCH 14" N.55°E, 28.47'- WAS NOTED AND REC'D. IN LIBER 2 OF LCR'S ON PAGE 338
 - B-5 [N1/4 COR S.18] WOOD POST A.MERRYWEATHER, D.S. 1847 (HEMLOCK 24"-S43°W-48 LINKS) (HEMLOCK 28"-N60°E-12 LINKS) NO RECORD EVIDENCE OF SUBSEQUENT CORNER RECOVERY OR MONUMENTATION
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - B-3 [N1/4 COR S.7] FOUND IN PLACE 1" IRON PIPE AS SET BY MYSELF IN 1979 AND AS DESCRIBED IN LIBER 2 OF LCR'S PAGE 338. W.BIRCH BT NOTED IN 1979 NCW DEAD WITH SCRIBING STILL VISIBLE, MCNABB'S WOOD POST NOW BADLY DETERIORATED. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE ORIGINAL CORNER FOSITION.
 - E-5 [N1/4 COR S.18] FOUND IN PLACE REMAINS OF SQ'D CEDAR POST WITH SCRIBING OF "1/4" STILL PARTIALLY VISIBLE. NO EVIDENCE OF GLO "BT'S ANCIENT BLAZE LINES FOUND RUNNING N-S & E-W FROM EXISTING CORNER MONUMENT. LOGGING OPERATIONS IN THIS AREA APPEAR TO HAVE HONORED WITHOUT DISPUTE, THIS POSITION FOR MANY YEARS. ACCEPTED EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER. MICHIG OF
- C. Description of monument for corner and accessories established to perpetuate locating the position of the

B-3 SET OVER EXISTING I.P. A BERNTSEN AINB30 ALUMN MON W/A 31/4" CAP STAMPED TO ID THE CORNER POSITION. CEDAR 16" CEDAR 9" CEDAR 8° MAPLE 6" SURVEY MONUMENT SIGN POST N30°W N72'E \$27° € S82°W SOUTH 28.70 29.80' 12.65 2.45' (TO FACE) 26.10'

B-5 REPLACED EXISTING WOOD POST W/A BERNTSEN AINB30 ALUMN MON W/A 3/1/4" CAP STAMPED TO ID THE CORNER POSITION.

MAPLE 10" HEMLOCK 10" MAPLE 10" HEMLOCK 10" SURVEY MONUMENT SIGN POST N55°W N71°∃ S48°E S59°W NORTH 17.64 26 80 8.78 29.70 2.62' (TO FACE)

NATE: REARINGS TO REFERRNCE ORIECTS ARE MACHITIC . DISCHARGES ARE HOLD WHILL IN MUST CHARGE OF THE ORIECT HULDS AND DE ORIECTALISM

	ANGUETIC - DIGINACES AND TO A MAIL IN THE CENTER OF THE GREECT UNSER	acimyanio dalon 60
$\mathcal{M} \mathcal{O} \mathcal{A}$. / /	•
Signed by M.P. SAUS	DateDate	
1/-	7, 7	
Surveyor's Michigan License No. 1697/2		,

8 PAGE 149

M. P DAVIS ND SURVEYOR

NO.

16926

IA.D