## FEB 2 2 1996

## COMMISSION

Approved By Delta County Land Survey Remonumentation Peer Group Under Act 345 Of P.A. OI 1990 On 10, 1995

For corners in		rement of Act 74, Mich.	A - Chrisman
DELTA	Located In:	Corner Code ##	
(County)	Losated III.	Corrier Code -44	
Public Land Survey	T38_N. R _24_W_ T R	L-13(6-H-13	hew 000 Oct 2-7 (995 1: 9:00 o'clock AM in Liber 8 page 111
O Constant Contant	T R		Walter C ZZ Reg. of Doods.
Property Controlling     in Section	S T R S T R		Control of the contro
<ol><li>Miscellaneous Property in Sec.</li></ol>	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No , R	ecorded Plat		ABCDEFGHIJKL
5. Private Claims L-13 [S1/4 COR \$.36	. M-13 fs	SE COR \$.36]	2 5 5 4 3 2
SAMS AS L-1 T37N R24W		(A-13 T38N Ř23W) & (A-1 T37)	4 7 8 9 10 11 12
do hereby certify that under require lines 1 and 2 above were in current manual of survey instrumanagement or by a decree of a above were in conformance with	in a field survey onBECENE utilements of P.A. 74, Michigan P.A. conformance with regulations an ctions of the United States Depart Court of Law and/or that the corne the rules of the Michigan Board a-established, monumented. re-n	of 1970, the corner pointsment of rules therefore as required tment of the Interior, Bureau of repoints mentioned in lines 3, 4 of Land Surveyors or by a Decre	ioned in the Land and 5 8 10 20 21 22 33 24 29 16 17 17 18 17 18 18 19 19 19 19 19 19 19 19 19 19 19 19 19
NOTE: Not more than 4 co on this certificate.	orners, all in the same town ar	nd range, may be recorded	12 31 32 33 34 35 36
L-13 [S1/4 COR S.36] JAMES	nonument and accessories and S. H., MULLETTE D.S., 1847-WOOD PI SUBSEQUENT CORNER RECOVERY OR	OST -(CEDAR 14"-N63"R-53 LI	:: NKS) (LYNN 14"-S45"W-10 LINKS)
M.S. MCMABB-1925-STAK  B. Description of corner evi L-13 [81/4 COR S.30] NO OR CORNER RESTORATION FO	ID STAXE IN PLACE AT INTERS OF (RE FROM PREVIOUS SURVEY-SET 1.4)  Idence found and/or method a RIGHNAL CORNER EVIDENCE FOUND & UND. ESTABLISHED CORNER POSITI TS COUNTY ROAD IMPROVEMENTS NO IDENCE AS TO THE LOCATION OF T	P. (COR FENCE POST-N68°E-36  pplied in restoring or reest; NO IDENTIFIABLE INDICATION ON AT JCT OF ANCLERT FENCEI RTH & EAST. ACCEPTED THIS F	.5') (BALM OF GILEAD STUMP 18"-N18°E-I7.5') ablishing corner: N OF SUBSEQUENT JINES WEST & SOUTH TO SOUTH AS BEING
M-13 [SE COR S.36] FOUND IN THE ELISTING MONUMENT THE ORIGINAL CORNER.	N PLACE AT THE APPROX. C/L PI AS BEING THE BEST AVAILABLE E	OF THE COUNTY ROAD HENABB'S VIDENCE AS TO THE LOCATION	1925 I.P. ACCEPTED OF THE POSITION OF
C. Description of monument	for corner and accessories es	stablished to perpetuate loc	cating the position of the corner.
L-13 SET A 5/8' X 18" REBAR CEDAR 12" CEDAR 8 S57'W S25'W 35.78' 26.30'	\$57°E	TO ID THE CORNER POSITION. RVEY MONUMENT SIGN POST SOUTH 2.60' (TO FACE)	
M-13 REPLACED EXISTING I.P.  CEDAR 6" CEDAR  N71'E S11'  37.24' 110.	E NORTH	GN POST NOTE: FARM FIELD NW & SW QU	DS IN THE
			ENTER OF THE OBJECT UNLESS NOTED OTHERWISE
Signed by	<i>j</i>	Date	10/24/95
Surveyor's Michigan License N	No. 16926	PACE 111	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAH., 1983