Approved By Delta County Land Survey Remonumentation Peer Group Under Act 345 Of

Of 1990 On Jan 20, 199 4

FEB 1 8 1994

expressed below:

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

howlin
an /

Ec	or corners in COMMIS	SION Filing Require	ment of Act 74, Mich. P.	A. 1970
DELTA (County)		Located In:	Corner Code ##	
1.	Public Land Survey	T 40 N R 23 W T R T R T R	I-7 & I-8	3000 January 21, 1994
2.	Property Controlling in Section	S T R S T R	<u> </u>	Desis County, Michigan
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
		Recorded Plat		A B C D E F G H I J K L M
0.	•	I-8 [W1/4 COR SEC 23]		2 6 5 4 3 2 1
l, do		, in a field survey on		, 5

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

- 10 11 12
- Description of original monument and accessories and/or subsequent restoration: I-7 [NW COR SEC 23] WOOD POST - A. MERRYWEATHER, D.S. - 1846 (CEDAR 18%-S20°E-8 LINKS) (HEMLOCK-N50°E-6 LINKS)

M.S. McNABB - 1913 - FOUND WOOD STAKE IN PLACE - SAID BY SETTLERS TO HAVE BEEN SET BY JOHN CRAIG WHILE COUNTY SURVEYOR BT STAKES BY MCNABB NW & SE 33'

- I-8 [W1/4 COR SEC 23] WOOD POST A. MERRYWEATHER, D.S. 1846 (BIRCH 20\*-EAST-13 LINKS) (HEMLOCK 12\*-N65\*E-25 LINKS) M.S. McNABB - 1920 - IDENTIFIED CORNER POSITION BY WOOD STAKE IN PLACE & "GLO" BIRCH BT - NEW BT FENCE POST S85°W-25'
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - I-7 INW COR SEC 23] FOUND IN PLACE A 1' IRON PIPE AT THE JCT OF FENCE LINES AS CALLED FOR IN THE RECORDS OF M.S. McNABB - NO EVIDENCE OF THE ORIGINALS AND AS THE FENCE LINES ARE NOW DOWN & IN POOR CONDITION UNABLE TO IDENTIFY MCNABB'S FENCE POST BT. ACCEPTED EXISTING MON-UMENT AS BEING A CAREFUL & FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER.
- I-8 [W1/4 COR SEC 23] NO EVIDENCE OF MCNABB'S 1920 WOOD POST FOUND EXTENDED LINE WEST FROM B1/4 CORNER SEC 23 & THRU C1/4 COR SEC 23, AS FD IN PLACE BY McNABB IN 1920, AND REESTABLISHED THE W1/4 COR ON THIS LINE AND PROPORTIONATE DISTANCE (BASED ON MCNABB'S MEASUREMENTS) WEST OF THE C1/4 CORNER, ACCEPTED THIS POSITION AS BEING A CAREFUL & FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER.



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
  - I-7 REPLACED EXISTING I.P. W/A 4" X 4" X 36" CONCRETE MONUMENT W/A BRASS CAP STAMPED TO ID THE CORNER POSITION SPRUCE 7" HEMLOCK 7" MAPLE 13" MAPLE 10\* SURVEY MONUMENT SIGN POST S72°W N70°W 123°W N56°E \$29°E 30.631 37.87 46.02' 9.16 2.10' (TO FACE)

I-8	SET	4 8	BELOW	EXISTING	ROADBED	A 5/8	}" X	18°	REBAR	W/A	3-1/	/ 4 <sup>11</sup>	AFAWN	CAP	STAMPED	TO	ID	THE	CORNER	POSITION	
-----	-----	-----	-------	----------	---------	-------	------	-----	-------	-----	------	-------------------	-------	-----	---------	----	----	-----	--------	----------	--

NW COR GARAGE YELLOW BIRCH POWER POLE SURVEY MONUMENT SIGN POST S86°E S65°E 531°W N86°W 87.60 46.381 48.921 23.38' (TO FACE)

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC & DISTANCES ARE TO A NAIL IN THE CENTER OF THE OBJECT UNLESS OTHERWISE NOTED

M. April 12/30/93 Signed by \_ Date Surveyor's Michigan License No. 16926