SUHVEY & REMONUMENTATION

OCT 0 3 2000	·	ender Act 345 of
		1 1 2000
SECTION	AND CORNER RECORDATION CER	STIFICATE Acting Chairman
بر) ا	Filing Requirement of Act 74, Mich. F	(III 10/11 = /
For corners in	-	
Located In:	Corner Code #	
.,,	N R 24 W K-06 K-07 R R R R R R R R R R R R R R R R R R R	RECORDED 28 July 2000 AT 9:00 O'CLOCK a.m. LIBER 9 PAGE 230
2. Property Controlling in Section S T 3. Miscellaneous S T	R R R	DELTA COUNTY MI REG. OF DEEDS
Property in Sec. S T K-06 [W1/4 COR SEC 13]	R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat		ABCDEFGHIJKLM
5. Private Claims I, M.P. DAVIS requirements of P.A. 74, Michigan P.A. of 1970, the conformance with regulations and rules therefore as religious of the interior. Bureau of Lainted States Department of the Interior Bureau of	y on JANUARY 00 do hereby state the corner points mentioned in lines 1 and 2 above equired in the current manual of survey instruction and Management or by a decree of a Court of Law	at under 4 7 3 9 10 11 12 12 13 14 15 15 14 13 15 15 14 15 15 14 15 15 14 15 15 14 15 15 15 14 15 15 15 15 15 15 15 15 15 15 15 15 15
that the corner points mentioned in lines 3, 4 and 5 a Board of Land Surveyors or by a Decree of a Co	above were in conformance with the rules of the Nourt of Law; established, re-established, monu	mented, 7
recovered, found as expressed below:		8 - 19 - 20 - 21 - 22 - 23 - 24 - 25 - 24 - 25 - 24 - 25 - 24 - 25 - 24 - 25 - 24 - 25 - 24 - 25 - 24 - 25 - 24 - 25 - 25
NOTE: Not more than 2 comers, all in the same on this certificate.	e town and range, may be recorded	9 10 -30 -29 -28 -27 -26 -25 11
		12 31 32 33 34 35 36
A. Description of original monument and acce	essories and/or subsequent restoration:	
-06 [W1/4 COR SEC 13] HARVEY MELLEN, D.S1 M.S.MCNABB-1919-ORIGINALS GONE SET "1/2 M.S.MCNABB-1934-FROM PREVIOUS SURVEY- (1852-WOOD POST (HEMLOCK 14" S58°E 18 L	
(-07 [NW COR SEC 24] HARVEY MELLEN, D.S189 M.S.McNABB-1917-ID FORM ORIGINAL Y.BIRG M.S.McNABB-1919-ID FROM PRVIOUS SURVEY M.S.McNABB-1934-ROAD ALIGNMENT SURVEY	52- WOOD POST (Y.BIRCH 16" S41°E 44 LI CH BT SE - SET BT STAKES NW & SE 33'	NKS)(CEDAR 22" N60°W Z4 LINKS)
		To Miles
B. Description of corner evidence found and	/or method applied in restoring or reestablis	shing corner:
C-06 [W1/4 COR SEC 13] NO CORNER MONUMENT FOR CEDAR STUMP BT TO THE SW & 5.8' NORTH A CAREFUL & FAITHFULL REESTABLISHMENT	OUND-REESTABLISHED THE CORNER POSITION OF ANCIENT FENCE LINE TO THE EAST. ACC	FROM MCNABB'S M. P. DAVIS
K-07 [NW COR SEC 74] NO CORNER EVIDENCE FOU AND W1/4 COR'S OF SEC 13 T40N R24 AND RECORDS OF M.S.MCNABB. ACCEPTED AS BEI THE POSISTION OF THE ORIGINAL CORNER.	IND - REESTABLISHED CORNER POSITION ON	
C. Description of monument for corner and a	ccessories established to perpetuate locati	ng the position of the corner:
K-06 SET A 5/8" X 18" REBAR W/A 3-1/4" ALUM CEDAR 09" ASH 07" N51"E S80"W 52.63' 64.22'	SPRUCE 22" SURVEY MONUMENT SIGN N68" W 26.50'(TO FACE)	N & RAISED TO GRADE W/A MONUMENT BOX POST
	M CAP STAMPED TO ID THE CORNER POSITION	N. C/L 5" STEEL GATE POST
K-07 SET A 5/8" X 18" REBAR W/A 3-1/4" ALUN RED PINE 08" C/L 2-1/2" STEEL GATE N68"E S72"E 34.83' 84.85'	E POST C/L 3-1/2" STEEL GATE POST S14"W 66.05'	52.35'
RED PINE 08" C/L 2-1/2" STEEL GAIE N68°E S72°E 34.83' 84.85'	S14"W 66.05' MAGNETIC-DISTANCES ARE TO A NAIL W/A D	s75°W

Dunty entation