## **SURVEY &** REMONUMENTATION

JUL 06 1998

Approved By Delta County

Land Survey	Remonumentation
Peer Group	Under Act 345 Of
LOf 1990 On	May 5 , 199

SECTION	JN	
---------	----	--

LAND CORNER RECORDATION CERTIFICAT Filing Requirement of Act 74. Mich. P.A.

For corners in			~ <			141	- (	
Delta	Located In:	Corner Code #						
(County)								
1. Public Land Survey	T <u>41N</u> R <u>18W</u> TR TR		Recorded				,	
Property Controlling in Section	S T R S T R		21 <u>9:00</u>				Page_ Reg. of L	
3. Miscellaneous	S T R		Delta Cou	inty, Mic	higan			
Property in Sec.	S R		Register of Deeds Stamp & File Numbe					
I, GERALD W. CARLSON do hereby state that under req mentioned in lines 1 and 2 ab required in the current manual of Bureau of Land Management of	uirements of P.A. 74, Michigan ove were in conformance with r survey instructions of the United or by a decree of a Court of La	February 24 , 19 98 , P.A. of 1970, the corner points egulations and rules therefore as States Department of the Interior, w and/or that the corner points	A B 1 2 -6-3 4 -7-5 6 -18-	C D :	E F (	G H	I J k	K L
•		he rules of the Michigan Board of ed, re-established, monumented.	8 19-	20-	21	22	23	24
recovered, found as expressed b	•	ou, le commune, monantitut	9 9					
NOTE: Not more than 2 con on this certificate.	rners, all in the same town and	I range, may be recorded	10 - 30 - 11	29	-28	27-	26	25-
A. Description of original mo M-8: <u>East Quarter corner Sec</u>	onument and accessories and/	or subsequent restoration:	12 31	32-	33	34-	35	36
	rvey notes describe the corner	monument as a set 1/4						
Section post (no corner monu	iment description given) refere	nced by:						

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

7" Hemlock

M-8:1998: No original corner evidence found. The corner was re-established equidistant and on line between the found Northeast and Southeast corners of Section 24. The distances North and South are 2658.60'. A Tom O'Brien 1/2" iron w/cap No. 21274 was found 6.60' Southwest of this position and upon consultation with Tom it was determined this 1/2" iron was set in the wrong position and was pulled out per Tom's concurrence.

N 80°W 38 L

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-8: 1998: Set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Delta County Survey Monument stamped to identify the corner. Established references with painted blazes and dh nails in:

12" Maple

N 48°E

19.00' (O'Brien NBT)

8" Cedar

S 51°E

14" Maple

53.80' (O'Brien NBT) 80.65' (O'Brien NBT) \$ 42°W

8" Maple

S 78°W 27.46'

S 57°W 42 L

Green steel fence post w/ Yellow Survey Marker sign N 74°E, 1.54'

Centerline North-South road

Surveyor's Michigan License No.

West. 20.25'

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.

24589

LIBER 0009 PAGE 077

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975

REVISED OCT., 1995

GERALD W CARLSON SURVEYOR No.