LAND CORNER RECURDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF-:	LOCATED IN-:	CORNER CODE NUMBER	1
1. PUBLIC LAND SURVEY	T. 41N S., R. 22W W.	м-9	
2. PROPERTY CONTROLL- ING IN SECTION——	N. E. V. S., R. W.		
3. MISCI LLANEOUS PROPERTY IN SECTION			
i. LOT NO, REC	ORDED PLAT	8 0, ,	
5. PRIVATE CLAIMS			
			REGISTER OF DEEDS STAMP AND FILING NUMBER
the corner points mentioned in li re-established, monumented, re-rand rules therefore as required in Bureau of Land Management or and 5 above were, in a field surve	mes 1 and 2 above were, in a fin monumented, recovered or restant the current manual of survey by a decree of a court of law. It mance with the rules of the Milmance with the rules of the Milmance with the rules of the Milmance McNabb Record Set iron pipe BTs W. pine 8"-N35E- N. pine S50W- MDOT plans 21-R-1 Sh Appr. Date 1933, shot Sec. Cor. 10.6' north	ored as expressed below and instructions of the United Structions of the United Structhermore, that the corne 9, found, recovered, resichigan State Board of Registrosequent restoration: Mel Dav Found 1 32.4' b tele. 24.6' b tele. b elec. eet 59 w this h of b of	of P.A. 74, Michigan P.A. of 1970, 19 84, established, lin conformance with regulations states Department of the Interior, repoints mentioned in lines 3, 4 tored, established or re-established ration for Land Surveyors or, by a lis, RLS Liber 4-Pg. 200/2" iron in blacktop rd. pole #19, N32°W-41.8" pole #18, N60°E-65.2 pole #107-S6°W-47.7"
M-86 (now a county road). B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: This section corner was re-established at 10.6' north of the centerline of Old M-86, (now a county road) as indicated on MDOT plans (21-R-1) and in line with the b of a graded road north (directly north of an existing 1/2" iron in a mon. box in the b of Old M-86. Measurements east and west agree with the stationing shown on MDOT plans (21-R-1) and the measurement north to the east 1/4 cor. of Sec. 24 agrees reasonably well with Marcus McNabb's recorded measurement. The location of this corner and the existence of the MDOT plans showing said location were brought to my attention by Mel Davis, RLS. Mel Davis stated to me that the "1/2" iron in blacktop'road" which he found and which is recorded in Liber 4 - page 200 is not the true section corner location and that the corner belongs 10.6' north of the road as shown C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:-over- 1" pipe 4" alum. cap. Power pole (pk) S6°W 58.3' Pipeline marker S36°W 47.6' 12" red pine N44°W 41.2' 19" w. pine N76°E 69.0' Iron rod in monument box b road, south - 10.6'			
SIGNED BY DATE 9-12-84			

FOR STATE AND UNITED STATES ACENCIES.

SURVEYOR'S MICHIGAN REGISTRATION NO. 21558