## SURVEY & REMONUMENT

SEP 1 8 1997

COMPAGE

Approved By Delta County

rand odivey nemonument	แเดก	
Peer Group Under Act 345	Of	
Peer Group Under Act 345 A. Of 1990 On Joles 23	199	,

Chairman

LAND CORNER RECORDATION CERTIFICATÉ Filing Requirement of Act 74, Mich. P.A. 1970

For corners in DELTA 28 July 1997 Located In: Corner Code ## (County) geleek a.m. 1. Public Land Survey T 41 N R 23 W C-11 C-12 212 R Delta Country, will Rep. of Directs Τ\_ \_ R 2. Property Controlling \_ T \_ R in Section Miscellaneous \_ T \_\_\_\_ R \_ Register of Deeds Stamp & File Number Property in Sec. S Т \_ , Recorded Plat \_ 5. Private Claims M.P. DAVIS , in a field survey on 16 JUNE/11 FEBRUARY do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 12 Description of original monument and accessories and/or subsequent restoration: C-11 [NW COR SEC 32]- A.MERRYWEATHER, D.S.-1847-WOOD POST (CEDAR 12"-N26"E-34 LINKS)(BIRCH 16"-S40"W-20 LINKS) M.S. Honabb-1918-IRON PIPE & STAKE -ID FROM ORIGINALS-SET BT STAKES NW & SE 33 M.S. McNABB-1947-FROM PREVIOUS SURVEY-FENCE LINES WEST & SOUTH CORNER FENCE POST WEST 4.5' C-12 [W1/4 COR SEC 32] A.MERRYWEATHER, D.S.-1847-WOOD POST (BIRCH 18"-EAST -19 LINKS) (BIRCH 10"-WEST -30 LINKS) M.S. McNabe-1918-FOUND IN PLACE IRON GAS PIPE & BT STAKE NW 33'-NEW BT'S N. GATE POST N80°E-19.5' & COR FENCE POST S30°E-38,4'

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - C-11 [NW COR SEC 32] FOUND IN PLACE 1"IRON PIPE 4.5' EAST OF REMAINS OF OLD CORNER FENCE POST, NO EVIDENCE OF MCNABB'S BT STAKES. ACCEPTED EXISTING MONUMENT AS BEING A CAREFUL & FAITHFUL PERPETUATION OF THE POSITION OF THE ORIGINAL CORNER
  - C-12 [W1/4 COR SEC 32] FOUND IN PLACE 1' IRON PIPE. ID SAME FROM COMPARISON OF MCNABB'S DISTANCE TO TO ADJOINING CORNERS WHICH CHECK WELL. ACCEPTED EXISTING MONUMENT AS THE BEST AVAILABLE EVIDENCE AS TO THE LOCATION OF THE POSITION OF THE ORIGINAL CORNER.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C-11 REPLACED EXISTING MONUMENT A BERNTSEN ALMB30 ALUM MON W/A 32/4" CAP STAMPED TO ID THE CORNER POSITION SPRUCE 5" MAPLE 8º SPRUCE 6" SURVEY MONUMENT SIGN POST

NORTH 7.88

S78°E

S8°W

WEST

6.53' 13.52' 2.24' (TO FACE)

C-12 REPLACED EXISTING MON W/A 4"X4"X36" CONC MON W/A 3" BRASS CAP STAMPED TO ID THE CORNER POSITION. SFRUCE 4"

N30'W

TAMARACK 5" N48°E

POWER POLE S40°W

SURVEY MONUMENT SIGN POST

C/L COUNTY RD 523 WEST

33.12'

40.58'

42.61'

EAST 1.55' (TO FACE)

NOTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC & DISTANCES ARE TO A NAIL IN THE CENTER OF THE OBJECT, UNLESS OTHERWISE NOTED.

Surveyor's Michigan License No. 16926

\_ Date \_

REVISED MAY 14, 1975 REVISED JAN., 1983

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971