## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Fo	or corners in															
<u>Delta</u>		Located In:		Corner Code ##												
1.	Public Land Survey		Ť Ť	R22W R R R	C-2, C-3.											
2.	Property Controlling in Section		† †	_ R												
3.	Miscellaneous	s	T	_ R		F	Registe	r of	Deed	s S	tam	<b>8</b> q	File	Nu	mbe	er
	Property in Sec.	s	T	_ R												
	Lot No , F						2	A B	c  -	D 5	E F	G	H - 3 —	-	) K	L _
				- 10			4	<u></u> - }-		$\dashv$	┝╬╌	+	-10	╁1	ņ—	<b>├</b>  2-
in cu Ma	o hereby certily that under re- lines 1 and 2 above were i urrent manual of survey instr anagement or by a decree of	quiremen n conforr uctions o a Court o	its of P.A. 74, I mance with re if the United f Law and/ori	Michigan P.A egulations a States Depa that the corn	9/88 . 19	ntioned d in the of Land 4 and 5	5 6 7 8	18-	1	7	16	+	-15	-	14	13-
Co	pove were in conformance wi burt of Law; established, opressed below;	th the rul re-establ	es of the Mic Ished, monu	higan Board imented, re-	of Land Surveyors or by a Dec monumented, recovered, fo	ree of a und as	9 10	——————————————————————————————————————	2		28	1	-27	-	26—	25
N	NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.					36										

- A. Description of original monument and accessories and/or subsequent restoration:
  - C-2. E1/4 corner of Section 6. Marcus McNabb, reset new stake & bearing stakes NE & SW 33'.
  - C-3. NW section corner of Section 8. Wood post. Cedar 10, S58W, 18 Lks. Cedar 14, N48E, 22 Lks.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - C-2. Marcus McNabb states that he found a wood stake and one OBT N70E, 152'. I found what I believe to be Marcus McNabb's "new stake" a sq. cedar post about 4" in diameter rotted off and fallen down. Old sq. post is in a N-S fence line and fits McNabb's mea. north to the NE section corner of Section 6 quite well. Set DNR monument in place of post.
  - C-3. Found fragments of cedar one of which has a definite hack mark partly healed over for the measuring notch from the southwest OBT. I could not tell exactly where the tree stood when alive but set the monument from the spot where the notch was found. No sign of the northeast OBT—swamp edge 108 Lks. East fits well and it is very near the single prop. mea. between the 1/4 corner, 1/2 mile north and the section corner 1 mile south.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-2. DNR Monument.	C-3. DNR Monument.
8" cedar, N75E, 18.4'	8" cedar, N4W, 68.7'
6" cedar, S52E, 6.6'	6" cedar, N70E, 27.7
6" cedar, S2E, 26.05'	8" cedar, S28E, 40.8
7" cedar, S88W, 28.4'	6" cedar, S5W, 61.2'

Signed by Lavil B. Bal	left
Surveyor's Michigan License No. 2155	