JAN2 3 2000

Approved By Detta County
Land Survey Remonumentation
Peer Group Under Act 345 Of
P.A. Of 1990 On Mic 28, 199 9
World Landing

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of A	ct 74, Mich. P.A. 1970
Located In: Corner Code #	
1. Public Land Survey T 43 N R 20 W T 44 N R 20 W T 43 NR 20 W T 43 NR 20 W T R	10.0.20 01-04-00 11.0.20 01-04-00 11.0.20 9 PAGE 18'5
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R K-01 [NW COR SEC 1] K-02 [W1/4 COR SEC 1]	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	
5. Private Claims	
	3
I, M.P. DAVIS , in a field survey on DECEMBER, 19 99 do requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines conformance with regulations and rules therefore as required in the current manual of sunited States Department of the Interior, Bureau of Land Management or by a decree that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 18 Board of Land Surveyors or by a Decree of a Court of Law; established, re-est recovered, found as expressed below:	s 1 and 2 above were in survey instructions of the of a Court of Law and /or 6 18 17 16 15 14 13 the rules of the Michigan
NOTE: Not more than 2 corners, all in the same town and range, may be rec	orded 9
on this certificate.	10 30 29 28 27 26 25
	11 32 33 34 35 36
	13 13 13 13 13 13 13 13 13 13 13 13 13 1
-01 ENW COR SEC 1] JOHN BURT, D.S1841-WOOD POST (W.PINE 12" S50°E BAY DE NOC LUMBER COMPANY-DATE UNKNOWN-UNRECORDED PLAT OF STONE -02 [W1/4 COR SEC 1] A.MERRYWESTHER, D.S. 1849-WOOD POST (BEECH 12" NO RECORD EVIDENCE OF CORNER RECOVERY AND/OR SUBSEQUENT MONUMENT	WEST 25 LINKS)(HEMLOCK 18" N80°E 42 LINKS)
 B. Description of corner evidence found and/or method applied in restorin -01 [NW COR SEC 1] FROM PREVIOUS VISITS TO THE AREA FOUND A 3/4" IRC STONER LAKE. WHEN I FIRST FOUND THIS MONUMENT IN 1971 IT WAS UN MONUMENT FROM RETRACEMENT OF PORTIONS OF THE UNRECORDED PLAT OF 	ON PIPE ON THE EAST SHORE OF M. P.
THE EXISTING MONUMENT AS BEING THE BEST AVAILABLE EVIDENCE AS I POSITION OF THE ORIGINAL CORNER.	TO THE LOCATION OF THE LAND SURVEYOR &
-02 [W1/4 COR SEC 1] NO CORNER EVIDENCE FOUND. REESTABLISHED CORNER PROPORTIONATE DISTANCE BETWEEN THE SECTION CORNERS 1/2 MILE TO 1	POSITION ON LINE WITH AND
C. Description of monument for corner and accessories established to per	petuate locating the position of the corner:
-01 SET,INSIDE THE EXISTING MONUMENT, A 5/8" X 18" REBAR WITH A3-1/ W.PINE 20" W.PINE 18" W.PINE 18" SUI M20°E S48°E S22°E 70.60' 38.27' 48.27'	'4" ALUM CAP STAMPED TO 1D THE CORNER POSITIONL. RVEY MONUMENT SIGN POST EAST 28.55'(TO FACE)
-02 SET A BERNTSEN A1NB30 ALUM MONUMENT WITH THE CAP STAMPED TO ID MAPLE 10" MAPLE 12' MAPLE 09" MAPLE N03°W N63°E SOUTH S65°V 16.18' 7.05' 2.18' 29.90	THE CORNER POSITION. 07" SURVEY MONUMENT SIGN POST J WEST
OTE: BEARINGS TO REFERENCE OBJECTS ARE MAGNETIC-DISTANCES ARE TO A P	HAIL W/A DELTA COUNTY REFERENCE TAG, UNLESS OTHERWISE NOTED.
Signed by Mif Sauri	Date
Surveyor's Michigan License No. 16926	