JAN 2 5 2000

SECTION

Approved By Delta County Land Survey Remonumentation Peer Group Under Act 345 Of

Of 1990 On Alec 28, 1999

est Schmeling Chairman

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		•]						
DELTA	Located In:	Corner Code #						A	
(County)				.G.	· · · · (01-0	4-0	0	
1. Public Land Survey	T_43 NF	19 W A-03 CORNER		3 F	2:00 9	01-01 0012 2012	19° ZZ.		
2. Property Controlling in Section	S TF	·				-, - , ,			
3. Miscellaneous Property in Sec.	S TF S TF	<u> </u>		Regi	cter of	Deeds S	tomn &	File No	umher
• •	[NE COR SEC 12] M	-04 [E1/4 COR SEC 12]		1/68	3(6) 01	Decas C	tamp a	7 110 144	2111201
4. Lot No, Reco				A B	C D	E F	G Н 	<u>I</u> J	K L !
requirements of P.A. 74, Michig	an P.A. of 1970, the cor	DECEMBER , 19 99 do hereb ner points mentioned in lines 1 and	d 2 above were in	3	8	9	10-	11-	12
conformance with regulations an United States Department of the that the corner points mentione	d ruies therefore as requi Interior, Bureau of Land d in lines 3, 4 and 5 abov	red in the current manual of survey Management or by a decree of a Co e were in conformance with the rule	instructions of the ourt of Law and /or as of the Michigan	6 18	1	716	15	14-	13
Board of Land Surveyors or b recovered, found as expressed b		of Law; established, re-establish	ed, monumented,	8 19	20	21_	22—	 23	24
NOTE: Not more than 2 cor on this certificate.	mers, all in the same to	wn and range, may be recorded		9 30	2'	9 28-	27—	26-	25
			-	11				<u> </u>	1

- A. Description of original monument and accessories and/or subsequent restoration:
- M-03 [NE COR SEC 12] Wm. BURT, D.S.-1841-WOOD POST (SPRUCE 08" N65"E 25 LINKS)(PINE 09" N80"W 19 LINKS)

 A.MERRYWEATHER, D.S.-1849-CORNER IN PLACE (HEMLOCK 08" S35"E 20 LINKS)(SPRUCE 09" N71"E 25 LINKS)

 BAY DE NOC LUMBER COMPANY-DATE UNKNOWN-MAP OF THE UNRECORDED PLAT OF ROUND LAKE SHOWS CORNER IN PLACE, NO DESCRIPTION GIVEN
- [E1/4 COR SEC 12] Wm BURT,D.S. 1841-WOOD POST (SPRUCE 06" N45°E 20 LINKS)(SPRUCE 06" N20°W 22 LINKS) NO RECORD EVIDENCE OF CORNER RECOVERY AND/OR SUBSEQUENT MONUMENTATION.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- M-03 [NE COR SEC 12] NO CORNER EVIDENCE FOUND REESTABLISHED CORNER POSITION ON LINE WITH AND PROPORTIONATE DISTANCE BETWEEN THE MEANDER CORNER ON THE SOUTH SHORE OF ROUND LAKE TO THE NORTH AND THE SE CORNER OF SECTION 13 TO THE SOUTH.
- M-04 [E1/4 COR SEC 12] NO CORNER EVIDENCE FOUND. REESTABLISHED CORNER POSITION AT THE MIDPOINT BETWEEN AND ON LINE WITH THE SECTION CORNERS 1/2 MILE TO THE NORTH AND SOUTH.



C.	Description of mo	nument for corner and	accessories es	tablished to perpetual	te locating the position of the con	1
M-03	SET A BERNTSEN CEDAR 12' N44'W 42.75'	A1NB30 ALUM MONUMENT HEMLOCK 14" N63°E 4.12'	WITH THE CAP MAPLE 08" S51°E 9.64'	STAMPED TO ID THE C W. PINE 20" S69"W 13.37'	CORNER POSITIONL. SURVEY MONUMENT SIGN POST SOUTH 2.02'(TO FACE)	Γ
M-04	SET A BERNTSEN W.PINE 14" N35°W	A1NB30 ALUM MONUMENT W.PINE 13' N45'E 6.83'	WITH THE CAP W.PINE 12" \$68°E 11.79'	STAMPED TO ID THE (W.PINE 14" S57°W 9.40'	CORNER POSITION. SURVEY MONUMENT SIGN POS NORTH 0.86'(TO FACE)	s

TE:	BEARINGS	TO REFEREN	CE OBJECTS	ARE MAGNET	IC-DISTANCES	ARE	TO .	A NAIL	W/A	DELTA	COUNTY	REFERENCE	TAG,	UNLESS	OTHERWISE	NOTED.

Signed by M.P. Anuis		Date	12/20/99	
0.9	16926			