bmmau to 139R 31W RECORDED LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 1998 DEC 14 TH 12: 24 For corners in Dickinson Located in: Corner Code # City of Kingsford REGISTER OF DEEDS DICKINSON COUNTY ROM MODERAL STREET 1. Public Land Survey T40NR 31W .T--1 3 SURVEY & REMONUMENTATION 2. Property Controlling NOV 1 5 1999 in Section 3. Miscellaneous Property in Sec. SECTION Register of Deeds Stamp & File Number 4. Lot No. , Recorded Plat 5. Private Claims I. Robert F. Perkins, in a field survey on Oct. 8, 1998, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: South & Corner Section 35 I-13 S.E. Corner Section 34 Post by James H. Mullett, D.S. Post by James H. Mullett, D.S. 1846 Original Bearing Trees Original Bearing Trees Birch 8" N50°E 18 Lk. Spruce Pine 6" N21°E 13 Lk. Maple 4" N31°W 7 Lk. Spruce Pine 6" N66°W 11 Lk. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: J-13 No Evidence of Original Corner I-13 No Evidence of Original Corner or Accessories Remains. or Accessories Remains. Found Capped Iron Pipe ± 3" below Asphalt Found Boat Spike inside of 11" Iron in Centerline Woodward Ave. as referred Pipe 6" below Asphalt Roadway. to in Certificate #429. Corner used on numerous prior Surveys include Ford Airport Survey to North and recorded Smeester Subdivision No. 1 to East. Description of monument for corner and accessories established to perpetuate locating the position of the corner: J-13 Placed 31 " Capped D.C. Remon. Corner in-I-13 Accepted above Pipe as Best Remainside existing $\hat{\mathbf{l}}^{ii}$ Iron Pipe and installed ing Evidence of Corner Location.
Placed 3! "Stamped D.C. Remon.
Corner inside Existing 1" Iron Pipe Monument Box. New Witnesses Db1. Oak 12" S49°W(M.B.) 79.20' Nail/Tag and installed Monument Box. P.Pole #N65-2449 N50°E(M.B.) 46.44' Nail/Tag New Witnesses P.Pole #N65-2448 S10°E(M.B.) 109.69'Nail/Tag Aspen 4" N37°W(M.B.) 81.00' Nail/Tag S.E. Cor. House Foundation N31°W(M.B.) 75.49 R.Pine 14" S36°W(M.B.) 53.70' Nail/Tag Nail-Top Fence Post N42°E(M.B.) 72.34' NW Flange Nut-F.H. S40°E(M.B.) 39.80 -igned by Placed Carsonite Marker 34.60' South. Date Oct. 24, 1998 4 urveyor's Michigan License No. 12027 F. SURVEY PEER GROUP AS THE OFFICE NO. 12027

COUNCE UNDER MICHIGAN PUBLICADO NO. 12027

EVA DE 1930 AT A MEETING HELD OF OMAL SUR ROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995 Lihon 1 COUNTY REPRESENTATIVE