LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Filing Requirement of Act 74, Mich. P.A. 197	0
For corners in	
Dickinson Located In: Corner Code #	
1. Public Land Survey	
T R	
Property in Sec. S TR	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	A B C D E F G H I J K L M
8 Sep 11 2000	2 6 - 5 4 3 - 2 1 - 1
I4 Oct 24 2000	3
I, <u>Stephan J. Szyszkoski</u> , in a field survey on, 19 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in	4 - 7 - 8 - 9 - 10 - 11 - 12 - 12
conformance with regulations and rules therefore as required in the current manual of survey instructions of the	5
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan	6 19 17 16 15 14 13
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,	7
recovered, found as expressed below:	8 19 20 21 22 23 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	9 10 20 27 26 25
on this certificate.	10 30 29 28 27 26 25
	11
	13 1 1 1 1 1 1 1
post on summit. W. Pine 14 S23E 17, Hemlock 4 S67W 0780.00 Set post corner Secs 2,3,10, (8-Sec. 2) West 1/16 corner, Section 2. Not established in the original survey.	,11.
B. Description of corner evidence found and/or method applied in restoring or reestablishing corn (I4) Original post and accessories were not recovered. The location of the topographic callinharmonious with the original record. Retracement in this township shows that the measures particularly along some of the N-S lines. We observed differences with the original record mentioned in the original record as being 2.5 chains south of this corner was recovered, the absolute reliance upon the topographic feature calls for the reestablishment of this corner and on a line of mean true bearing between Section corners 2715.4' north and south, being p measurement. (8-Sec. 2) Established the corner midway and on a straight line between Center of Section 1 From the position thus established, I found a metal "I" fence post, not of record, \$50W, 75	ls along this line is substanially ments along the lines were poorly made, of over 300'/mile. Though the ledge e poor quality of the measurements precluded. Accordingly, I monument the corner midway reportionate to the original record 325.0' east and Quarter corner 1325.0' west.
C. Description of monument for corner and accessories established to perpetuate locating the pose (I4) Set 1"ID iron pipe with 4" aluminum (8) Set 1"ID iron pipe with 4" aluminum MDNR cap. Blazed and scribed: MDNR cap. Blazed and scribed: 3" W.Ash S50E 10.1' "1/4S NBT" 7" Sugar N16E 45.7' "1/16S BT" 4" W.Spruce S20E 25.4' do 13" Y.Birch S83W 56.4' do 13" R.Pine S23W 40.0' do 9" Y.Birch S36W 58.0' do 10" R.Oak S55W 67.1' do 5" Balsam S33E 16.9' do Squared a 3" aspen S55E 2.5' to center. Bearings are magnetic. Distances to notch in lower blaze. The mon. is set in a 2ft. dia. rock mound.	STEPHAN J. SZYSZKOSKI LAND SURVEYOR NO. 33986

Surveyor's Michigan License No.